

SURVEY &  
REMONUMENTATION

MAR 19 1998

1997 Newaygo County Remonumentation Project

NEWAYGO COUNTY  
REGISTER OF DEEDS  
LINDA M. BROWN

SECTION

LAND CORNER RECORDATION CERTIFICATE  
FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'98 MAR 6 PM 12 34

*Linda M. Brown*

For corners in  
Newaygo  
(County)

Located in:

Corner Code #

1. Public Land Survey

T 11N R 12W

T 12N R 12W

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

K-1 ✓

K-13

VOL. 2

68

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, Norman L. Ochs, in a field survey on July 8, 1997,  
do hereby certify that under requirements of P. A. 74, Michigan P.A. of 1970, the corner  
points mentioned in lines 1 and 2 above were in conformance with regulations and rules  
therefore as required in the current manual of survey instructions of the United States  
Department of the Interior, Bureau of Land Management or by a decree of a Court of  
Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in  
conformance with the rules of the Michigan Board of Land Surveyors or by a  
Decree of a Court of Law; established, re-established, monumented, re-monumented,  
recovered, found as expressed below:

Note: Not more than 4 corners, all in the same town and range, may be  
recorded on this certificate.

Northwest Corner, Section 1, Grant Township, Newaygo County, Michigan  
Southwest Corner, Section 36, Brooks Township, Newaygo County, Michigan

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Brookfield and Hodgson 1838  
18" Pine S58½°W 56 Links (36.96') #1  
24" Pine S63°E 68 Links (44.88') #2

Lyle S. Shepherd R.L.S. #503  
Witness Book Number 2 Page 154  
8" Black Oak Northeast 16.2' #3

Ralph A. Smith R.L.S. #3421  
1959 Book 70 Page 1  
Gas Pipe  
Tower Line West 47' #4  
10" Black Oak S35°E 54.75' #5  
Leg Tower N45°W 52.5' #6  
14" Yellow Oak S64½°E 79.3' #7  
8" White Oak N67½°E 57.8' #8

OVER

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR  
REESTABLISHING CORNER:

Found 1½" X 33" Iron pipe with spike in center and in the centerline of East - West gravel road and the centerline of gravel  
road going South is 18 feet West and the centerline of gravel road going North is 21 feet West. The condition of the  
recorded witnesses are: #1 thru #3 gone, #4 thru #7 good condition, #8 gone, #9 thru #11 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING  
THE POSITION OF THE CORNER:

Removed 1½" X 33" Iron pipe and spike and set a 4" diameter Harrison cast iron monument 36" long marked "County  
Surveyor" as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the  
original corner.

Centerline of Power Line West 48' #4  
20" Black Oak S25°E 55.05' Found spike in West side of tree. #5  
Southeast leg Tower N40°W 52.60' @ ground. #6  
28" Black Oak S61°E 79.3' Set spike with tag in Southwest side of tree. #7  
14" Black Oak S82°W 117.45' Found spike with tag in Southeast side of tree. #9  
Power Pole N75°E 75.47' Found p.k. nail in Northwest side of pole. #10  
Southwest Corner Tower N49°W 64.9' @ ground #11



Signed by Norman L. Ochs

Norman L. Ochs

Date September 8, 1997

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Approved by Peer Review Group on September 9, 1997

Norman L. Ochs, County Representative.

*N.L.O.*