

# SURVEY & REMONUMENTATION

MAR 02 1999

1998 Newaygo County Remonumentation Project

NEWAYGO COUNTY  
REGISTER OF DEEDS  
LINDA M. BROWN

LAND CORNER RECORDATION CERTIFICATE  
FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'99 FEB 17 PM 3 39

## SECTION

For corners in  
Newaygo  
(County)

Located in:

Corner Code #

*Linda M. Brown*

1. Public Land Survey

T 13N R 11W

F-1

T      R     

T      R     

T      R     

2. Property Controlling  
in Section

S      T      R     

S      T      R     

3. Miscellaneous  
Property in Sec.

S      T      R     

S      T      R     

4. Lot No.                 , Recorded Plat                 

5. Private Claims   

VOL. 2

236

Register of Deeds Stamp & File Number

I, Norman L. Ochs, in a field survey on June 15, 1998, do hereby certify that under requirements of P. A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

**Note: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

North One Quarter Corner, Section 4, Big Prairie Township, Newaygo County, Michigan.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

### A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Not set.

Norman L. Ochs R.L.S. #22439

April 4, 1979 Set 1/2" Rod half way and on line between the Northeast and the Northwest Section Corners. Woods line going North is 33 feet East of Corner.

4" - 5" Twin Maple S30°±E 52.98' #1

16" Red Oak N15°±E 50.00' #2

12" Red Oak N45°±W 46.20' #3

South One Quarter corner, Section 33, T14N R11W East 33.12' #4

### B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 1/2" X 18" Rerod and the centerline of the East and West bituminous road is South 3.5'±. The condition of the recorded witnesses are: #1 dead, #2 and #3 stump, #4 good condition.

### C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Rerod and set a 2 3/4" X 20" Harrison cast iron monument marked "County Surveyor" in new 8" diameter monument box as a substantial marker for the section corner.

10" - 4" Dead Twin Maple S23°E 52.95' Found spike in West side of tree. #1

24" Stump N15°E 50.00'± to centerline. #2

18" Stump N46°W 46.12' Found spike in Easterly side of stump. #3

South One Quarter Corner, Section 33, T14N R11W (2 3/4" X 20" Harrison cast iron monument) East 33.08' #4

6" - 6" - 6" Triple Maple (blazed) S30°E 61.85' Set spike with tag #22439 in West side of tree.

18" Red Oak (blazed) N46°W 46.70' Set spike with tag #22439 in Southeast side of tree.

6" Box Elder (blazed) N65°E 65.13' Set spike with tag #22439 in South side of tree.

8" White Pine (blazed) S10°W 30.23' Set spike with tag #22439 in East side of tree.

1/2" X 18" Rerod with cap #22439 South 33.01'

Signed by *Norman L. Ochs*

Norman L. Ochs

Date October 15, 1998

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971

Approved by Peer Review Group on November 10, 1998

Norman L. Ochs, County Representative.

Revised May 14, 1975

Revised Jan., 1983

