

SURVEY & REMONUMENTATION

MAR 19 1998

1997 Newaygo County Remonumentation Project

NEWAYGO COUNTY
REGISTER OF DEEDS
LINDA M. BROWN

SECTION

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT of Act 74, Mich. P.A. 1970

'98 MAR 6 PM 12 37

Linda M. Brown

For corners in
Newaygo
(County)

Located in:

Corner Code #

1. Public Land Survey

T 15N R 12W

C-5

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

VOL. 2

130

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Norman L. Ochs, in a field survey on October 1, 1997, do hereby certify that under requirements of P. A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Note: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Northwest Corner, Section 17, Monroe Township, Newaygo County, Michigan.

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Milton Nye Resurvey 1856
8" Spruce Pine N64°E 91 Links (60.06') #1
12" Spruce Pine S87½°W 132 Links (87.12') #2

L.M. Gibson (Junior Forester U.S.D.A.)
December 27, 1939 Squared Stakes
14" White Pine N79°W 15.5 Links (10.23') #3
16" White Pine S16°E 42 Links (27.72') #4

Delos G. Anderson (County Surveyor)
July 7, 1898 Book A Page 227
Old Government Corner

Patrick A. Salisbury R.L.S. #13594
1972 Set 5" X 5" X 5' Concrete monument with brass cap. 16" above ground
6" Maple S74°W 13.14' #5
6" Black Oak S26°W 12.12' #6
6" - 12" Twin White Oak N34°W 32.23' #7
12" Jack Pine N15°W 2.91' #8
Forest Service Post West 17.0' #9

William Fries, Jr. R.L.S. #30389
LCRC #948 February 16, 1990
Concrete Monument found.
12" Maple S74°W 13.14' #5
18" - 7" Twin White Oak N34°W 32.23' #7
9" Black Oak S26°W 12.12' #6
12" Dead Jack Pine N05°W 2.91' #8

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 5" X 5" square concrete monument with brass cap #13594. The condition of the recorded witnesses are: #1 thru #3 gone, #4 found stump but at S10°W 27.7' to face, #5 thru #7 good condition, #8 dead, #9 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted concrete monument as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

24" Pine Stump S16°W 27.7' to face. #4
18" Maple with blaze S87°W 13.14' Set spike and tag in South side of tree. #5
14" Black Oak S31°W 12.18' Set new spike and tag over old spike in West side of tree. #6
34" Forked White Oak N27°W 32.39' Found spike in West side of tree. #7
14" Pine (Dead) N12°W 2.93' Found spike in East side of tree. #8
4" X 4" Forest service post N86°W 17.13' to face. #9

Signed by Norman L. Ochs
Norman L. Ochs

Date October 7, 1997

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Approved by Peer Review Group on November 11, 1997

Norman L. Ochs, County Representative.

N.L.O.

