

MAR 13 2000

SECTION

1999 Newaygo County Remonumentation Project

NEWAYGO COUNTY REGISTER OF DEEDS
LINDA M. BROWN

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT of Act 74, Mich. P.A. 1970

00 FEB 28 PM 1 17

For corners in
Newaygo
(County)

Located in: T 15N R 12W

Corner Code # K-11

1. Public Land Survey
T 15N R 12W
T R
T R
T R

2. Property Controlling
in Section
S T R
S T R

3. Miscellaneous
Property in Sec.
S T R
S T R

4. Lot No. , Recorded Plat

5. Private Claims

Linda M. Brown

VOL. 2 363

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Norman L. Ochs, in a field survey on October 12, 1999, do hereby certify that under requirements of P. A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Note: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Northeast Corner, Section 35, Monroe Township, Newaygo County, Michigan.

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Milton Nye 1856 Resurvey
22" Elm N84°E 33 Links (21.78') #1
15" Black Ash S60°W 14 Links (9.24') #2

1913 Michigan State Highway Department
Plat 9-G-19
Centerline Station 99 + 15.0
U.S.G.S. BM 1151.687 - West 9 feet and North 2 feet
(Iron Post Stamped "Prim. Trav. Sta. No. 18, Mich. 1,153, 1916" #3

Delos G. Anderson (County Surveyor)
Book A, Page 192 September 16, 1885
Measured 80 Chains (5280') from the Southwest Corner to the Northwest Corner and measured 39.40 Chains (2600.4') from the Southwest Corner to the South One Quarter Corner of Section 25.

Newaygo County Road Commission Sheet
Set 1/2" Pipe
14" Elm South 21.85' #4
8" Basswood S70°W 21.0' #5
8" Twin Basswood N30°W 26.20' #6

OVER

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found 1 1/2" Pipe with brass cap at surface in the centerline of the bituminous road going North and the bituminous road going West. There is no other occupation. The condition of the recorded witnesses are: #1 thru #6 gone, #7 thru #14 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted 1 1/2" Pipe with brass cap as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the position of the original corner.

- Power Pole S27°W 48.60' Found spike in Northwest side of pole. #7
- Power Pole N18°W 131.89' Found spike in Northwestern side of pole. #8
- 8" Red Oak S65°E 25.63' Found spike in North side of tree. #9
- #20 Gas Marker N32°E 86.11' #10
- 10" Ash S50°E 33.33' Found spike in Westerly side of tree. #11
- 12" Ash S40°E 44.00' Found spike in Westerly side of tree. #12
- 20" White Pine S05°E 66.93' Found spike in West side of tree. #13
- 12" Red Oak S22°W 99.45' Found spike in East side of tree. #14

Signed by Norman L. Ochs Date October 22, 1999
Surveyor's Michigan License No. 22439



Approved by Peer Review Group on December 16, 1999
Norman L. Ochs, County Representative.

Form approved by Michigan State Board of Land Surveyors, Jan 28, 1971
Revised May 14, 1975
Revised Jan., 1983

N.L.O.

A. Description (cont.)

Norman L. Ochs R.L.S. #22439

October 2, 1979 Set 1/2" Rod by using the Michigan State Highway Department's measurement of 3956.6 feet from the North One Eighth Corner on the West section line to the Southwest Corner of Section 25.

Power Pole S25°W 48.72' #7

Power Pole N20°W 131.93' #8

5" Red Oak S65°E 25.63' #9

#20 Gas Marker N40°E 86.11' #10

Corey J. Hughes R.L.S. #20706

LCRC #1180 June 1992

Found 1/2" Rod by Norman L. Ochs R.L.S. #22439, Set 1 1/2" Pipe and brass cap.

8" Ash S36°E 37.15' #11

9" Ash S25°E 42.76' #12

14" White Pine S13°W 65.71' #13

9" Red Oak S37°W 98.26' #14

SURVEY &
REMONUMENTATION

MAR 13 2000

SECTION