

LIBER 17932 PG 786
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oakland

Located in: Farmington Twp. Corner Code #

1. Public Land Survey

T 1-N R 9-E F-11
T R SURVEY &
T R REMONUMENTATION
T R
S T R
S T R
S T R
S T R
MAR 21 2000
SECTION

2. Property Controlling
in Section

3. Miscellaneous
Property in Sec.

4. Lot No. , Recorded Plat

5. Private Claims

I, John N. Redash, in a field survey on March 4, 1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1817	Set post	S. Carpenter	N/A	G.L.O. notes
1971	Found iron in monument box	G. Stonerock	#13601	Survey L5829, P705
1972	Found iron in monument box	G. Stonerock	#13601	L.C.R.C. L5830, P545
1974	Ref. to L.C.R.C. L5830, P545	D. Vitins	#17324	Survey L6333, P408 & Survey L6333, P410
1976	Iron bar in box	R. Roskelly	\$18663	Survey L6865, P611

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A found 1/2" iron rod in a monument box currently occupies this corner at the intersection of Gill Road and 9 Mile Roads. Current measurements match 3 ties each from Survey L5829, P705, L.C.R.C. L5830, P545, and Survey L6865, P611. Field measurements were made between the following corners:

E-11 to F-11	F-11 to G-11
2634.78 Meas.	2631.81 Meas.
2623.50 G.L.O.	2623.50 Rec. G.L.O.
	2632.12 Rec. plats L67, P2 & L36, P31
	2631.51 Rec. tax maps 23-28G & 23-28H

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I placed a 2" diameter brass cap stamped "Oakland County Remonumentation PS#37281" on the existing 1/2" iron in monument box. Witness ties are as follows:

S. 80° E.,	641.06'	Found concrete monument at the N.W. corner, 9 Mile & Cass
S. 40° E.,	61.62'	P.K. nail and remon. washer N.E. face U-pole
S. 47° W.,	54.28'	P.K. nail and remon. washer N.W. face U-pole
N. 50° W.,	80.48'	P.K. nail and remon. washer N.E. face U-pole
N. 45° E.,	56.41'	P.K. nail and remon. washer S.E. face U-pole

The selected location is accepted by me and generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by John N. Redash
Surveyor's Michigan License No. 37281

Date March 24, 1997

