

MAY 11 1950 84083

LIBER 15397 PAGE 592

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970  
Commerce Twp.

For corners in Oakland

	Located In:	Corner Code #
1. Public Land Survey	T 2N R 8E	F-13
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

1.00 MISCELLANEOUS RECORDING

2.00 REMONUMENTATION

11 MAY 95 9:05 A.M. RECEIPT# 12B  
PAID RECORDED - OAKLAND COUNTY  
LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

Compliance with  
ACT 345, P.A. 1990

APPROVED ON: 1-23-95  
OAKLAND COUNTY REMONUMENTATION  
PEER GROUP COMMITTEE  
Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat  
5. Private Claims

I, David Pawlaczyk, in a field survey on December 5, 1994, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1816 Post	G.L.O.	A. Holmes	N/A	Notes
1973 Iron in mon. box	L.C.R.C.	R. Wade	#11868	L6246 P584
1980 Monument box	Survey	R. Kostecke	#12584	L7706 P898
1990 P.K. Nail	L.C.R.C.	F. DeDecker	#8386	L11645 P218

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A P.K. nail in asphalt pavement currently occupies this corner. The following ties were used to verify and recover its position:  
2 ties match L.C.R.C. L6246 P584 and L11645 P218  
2 ties match survey witnesses from L 7706 P898

Field measurements were made between the following corners:

F-13 to E-13	2651.67	meas.		
	2640.00	rec.	G.L.O.	Notes
	2651.64	rec.	Survey	L11645 P211

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced the P.K. nail in asphalt pavement with a 5/8" x 24" iron rod with a 2" diameter brass cap stamped "Oakland County Remonumentation P.S. #17632" with a new monument box.

N.81° E.	174.44'	P.K. nail and O.C.R. tag in S. face utility pole
S.35° W.	37.20'	P.K. Nail and O.C.R. tag in N.W. face utility pole
N.77° W.	137.97'	P.K. nail and O.C.R. tag in S. face M.B.T. pole
N.20° E.	32.42'	P.K. nail and O.C.R. tag in W. face utility pole

The selected location is accepted by me and generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by [Signature]  
Surveyor's Michigan License No. 17632

Date 2-16-95

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN. 1983

OK - T. SMITH

