

COPY

LIBER 19548 PG 781

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oakland
(County)

Located in: Corner Code #
West Bloomfield Township

1. Public Land Survey

T2N R9E F-11

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. Recorded Plat

5. Private Claims

\$ 9.00 MISCELLANEOUS RECORDING
\$ 2.00 REMONUMENTATION
11 FEB 99 9:01 A.M. RECEIPT SA
PAID RECORDED - OAKLAND COUN
G. WILLIAM CADWELL
CLERK/REGISTER OF DEEDS

Compliance with
ACT 345, P.A. 1990

APPROVED ON: 2-3-99 JS
OAKLAND COUNTY REMONUMENTATION
PEER GROUP COMMITTEE

Register of Deeds Stamp & File Num

I, Huston K. Kennedy, in a field survey on October 26, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

| A | B | C | D | E | F | G | H | I | J | K | L |
|----|----|----|----|----|----|----|---|---|---|---|---|
| 1 | | | | | | | | | | | |
| 2 | 6 | 5 | 4 | 3 | 2 | 1 | | | | | |
| 3 | | | | | | | | | | | |
| 4 | 7 | 8 | 9 | 10 | 11 | 12 | | | | | |
| 5 | | | | | | | | | | | |
| 6 | 10 | 17 | 16 | 15 | 14 | 13 | | | | | |
| 7 | | | | | | | | | | | |
| 8 | 19 | 20 | 21 | 22 | 23 | 24 | | | | | |
| 9 | | | | | | | | | | | |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 | | | | | |
| 11 | | | | | | | | | | | |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 | | | | | |
| 13 | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

1817-GLO Carpenter, D.S.; Set Post 18" Hickory N72°E 4 ½ Links; 4" Red Budd S76 ½°W 24 Links

1.) 1988-DeKeyser, PS #30080; LCRC L.10730, Pg.183 - Fnd a PK Nail

2.) 1988-DeKeyser, PS #30080; Survey L.11085, Pg.890 - Fnd a PK Nail w/spotter, used same wit as 1988 LCRC

3.) 1987-Marini, PS #26462; Unrecorded Survey - Fnd a Monument

4.) 1962-Oakland County Road Commission Unrecorded Witnesses - Fnd a "x" in pavement

5.) 1962-Oakland County Road Commission Unrecorded Witnesses - Fnd a Iron Pin

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1998-Kennedy Surveying, Inc. - Kennedy, PS #17623 - Fnd a PK Nail 0.70 feet North of the existing centerline of Maple Road extending East & West, which has a bituminous surface, which I did not accept. A tree row extends to the North & South. I set the corner based upon the State Plane Coordinates provided by West Bloomfield Township.

Witnesses from LCRC #1, Survey #2, Unrecorded Surveys #3, 4 & 5 were used to recover and verify the location of the PK Nail, which I did not accept.

Field Measurements on back side of LCRC

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: PS #17623 in a new Monument Box

S33°E 94.51' Set Mag Nail & Remon Washer NE face 8" Maple

S03°E 40.32' Set Mag Nail & Remon Washer East face Power Pole

N06°W 52.45' Set Mag Nail & Remon Washer West face Power Pole

N63°W 210.52' Set Mag Nail & Remon Washer NE face Power Pole

North 74.76' Fnd ½" Iron Rod

South 60.10' Fnd 4" diameter Concrete Monument

South 53°W 0.84' Fnd PK Nail

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence the position of the original corner.

Signed by:

Date 2-5-99

Surveyor's Michigan License No.

17623