

COPY

LIBER 18319PG442

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oakland

(County)

Located in:

Corner Code #

West Bloomfield Township

1. Public Land Survey

T2N R 9E M-1

2. Property Controlling in Section

S

T

R

SECTION 8

3. Miscellaneous Property in Sec.

S

T

R

SECTION 8

4. Lot No. Recorded Plat

5. Private Claims

I, Huston K. Kennedy, in a field survey on January 3, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
1817-GLO Carpenter, D.S.; Set Post 9" Ash N51°W 3 Links; 10" Ash S05°E 6 Links
1.) 1995-Smith, PS #31608; LCRC L.15292, Pg.364 - Fnd Concrete Monument

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
1998-Kennedy Surveying, Inc. - Kennedy, PS #17623 - Fnd a 4" diameter Concrete Monument with a 3/8" Iron Rod .50 feet below the surface. This corner is a common corner with the Northwest corner of Section 6, Bloomfield Township (A-1) the Southeast corner of Section 36 Waterford Township (M-13) and Southwest corner of Section 31 Pontiac Township (M-1).

Witnesses from LCRC #1 were used to recover and verify the location of the found 4" Concrete Monument with 3/8" Iron Rod

I accepted the found 3/8" Iron Rod as the best evidence of the original corner position.

FIELD MEASUREMENTS BETWEEN

M-1 to M-2

GLO = 49 chains or 3234.00 Ft. 320.24 Ft. (Calculated)

M-1 to L-1

No GLO
2608.90 Ft. (Calculated)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
M-1 I placed a 2" diameter brass cap stamped Oakland County Remonumentation, PS #17623 on the existing 4" diameter Concrete Monument
Due South 49.97' Set PK & Remon Washer East face Power Pole
Due East 4.80' West face 6" Steel fence post
N85°W 39.50' Set PK & Remon Washer NW face 26" Maple
S21°W 17.10' Set PK & Remon Washer SE face 31" Maple
S85°W 80.31' NE corner of house #1497

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by: Huston K. Kennedy

Date 3-12-98

Surveyor's Michigan License No. 17623

\$ 7.00 MISCELLANEOUS RECORDING

\$ 2.00 REMONUMENTATION

9 APR 98 1:47 P.M. RECEIPT# 1084

PAID RECORDED - OAKLAND COUNTY

LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

Compliance with
ACT 345, P.A. 1990

APPROVED ON: 3-4-98 JS
OAKLAND COUNTY REMONUMENTATION
PETER GROUP COMMITTEE

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

