

COPY

LIBER 18604 PG 264

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oakland

(County)

Located in:

West Bloomfield Township

Corner Code #

1. Public Land Survey

T2N R9E M-5

T R

T R

T R

2. Property Controlling in Section

S T R

S T R

3. Miscellaneous Property in Sec.

S T R

S T R

SECTION

4. Lot No. Recorded Plat

5. Private Claims

I, Huston K. Kennedy, in a field survey on January, 1998, hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

## A. Description of original monument and accessories and/or subsequent restoration:

1817-GLO Carpenter, D.S.; Set Post 40" White Oak S88 1/2°W 67 Links; 40" White Oak N37°E 1.73 Links

1.) 1987-Lohff, PS #13791; Unrecorded Survey - Object found not stated, no witnesses

2.) 1987-Lohff, PS #13791; Unrecorded Survey - Object found not stated, no witnesses

3.) 1987-Lohff, PS #13791; Unrecorded Survey - Object found not stated, no witnesses

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1998-Kennedy Surveying, Inc. - Kennedy, PS #17623 - Fnd a 3/4" Iron Pipe 2" below the ground surface with a fence/plat line extending to the North, South &amp; West.

## FIELD MEASUREMENTS BETWEEN

## M-5 to L-5

No GLO, corner falls in a lake

"SUPERVISOR'S PLAT NO. 9" + "BEL-AIRE" + Parcels (Sec 13) = 2613.60 Ft.

"SHOREWOOD HILLS" + "SUPERVISOR'S PLAT NO. 9" (Sec 12) = 2613.45 Ft.  
2612.59 Ft. (GPS-CAL-MEA)

## M-5 to M-4

GLO = 40 chains or 2640.00 Ft.

"SHOREWOOD HILLS" + "LONG LAKE SHORES" + "THE WOODS OF BLOOMFIELD HILLS" (Sec 12) = 2671.06 Ft. (CAL)  
2669.75 Ft. (GPS-CAL-MEA)

## M-5 to M-6

GLO = 40 chains or 2640.00 Ft.

No plat or sidwell distances

Corner falls in a lake

2647.70 Ft. (GPS-CAL-MEA)

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-5 I replaced the found 1/2" Iron Pipe with a 4" diameter Concrete Monument with 2" diameter brass cap stamped Oakland County Remonumentation PS #17623

N50°E 8.00' Fnd Mag Nail &amp; Remon Washer SE face 8" Cherry

S46°W 18.90' Fnd Mag Nail &amp; Remon Washer stamped #24598 NW face 19' Poplar

Due East 24.70' Fnd Mag Nail &amp; Remon Washer stamped #24598 South face 29" Willow

N36°W 27.15' Fnd Mag Nail &amp; Remon Washer stamped #24598 SW face 27" Oak

S22°E 13.50' Center of Sanitary Manhole Rim

South 77°East 0.80 feet found 1/2" iron pipe

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by:

Date

Surveyor's Michigan License No.

\$ 7.00 MISCELLANEOUS RECORDING

\$ 2.00 REMONUMENTATION

18 JUN 98 8:18 A.M. RECEIPT# 40A

PAID RECORDED - OAKLAND COUNTY

LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

Compliance with  
ACT 345, P.A. 1990APPROVED ON: 4/21/98 JS  
OAKLAND COUNTY REMONUMENTATION  
PEER GROUP COMMITTEE

Register of Deeds Stamp &amp; File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	16		17		18		19		20		21		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

