

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

ror	corners in			\$ 7.00 MISCELLANEOUS RECORDING	
0	akland	Located In: Co	orner Code #	\$ 2.00 REHONUMENTATION	
	(County)	West Bloomfield Townshi	ip	14 JAN 99 12:56 P.M. RECEIPTS 2004	
	Traffic Land Orman	TAN DOE		PATO RECORDED - DAM AND CONTROL	
1. ?	Public Land Survey	T <u>2N</u> R <u>9E</u> T R	<u>M-8</u>	G. WILLIAM CACOELL	
		Ť Ř	25 5 25 M p	CLERK/REGISTER OF TERRE	
		T R	1 12 CO BOA (ST	Compliance with	
	Property Controlling	STR	and the source of	ACT 345, P.A. 1990	
	n Section Miscellaneous	ST_R_	RR Z I Z880	APPROVED ON: 10-15-58 55	
Property in Sec. S T R			OAKLAND COUNTY REMONUMENTATIO: PEER GROUP COMMITTEE		
	•		OFOTION:	Register of Deeds Stemp & File Numbe	
4 (1	at Na - Ma	and at Dist	SECTION 1	Register of Deeds Startip & Fire Holling	
4. Lot No, Recorded Plat					
J. ,	Trate Olanna			2 - 6 - 5 - 4 - 3 - 2 - 1	
. 1	kreton 16. Kommonki.	A A A		4 -7 - 8 - 9 - 10 - 11 - 12	
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in					
conformance with regulations and rules therefore as required in the current manual of survey instructions of the					
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan				6 18 17 16 15 14 13	
	rd of Land Surveyors or invered, found as expressed	by a Decree of a Court of Law; estable below;	ished, re-established, monumented,	B 19 20 21 22 23 24	
	•				
NO		orners, all in the same town and rang	e, may be recorded		
	on this certificate.			10 30 29 28 27 26 25	
		·		12 - 31 32 33 35 36 35 36 37 36 37 37 36 37 -	
В.	 4.) 1980-Sabatini, PS #24141; Survey L.7767, Pg.314 – Object fnd not stated, no witnesses 5.) 1997-Kapelczak, PS #24598; Unrecorded LCRC – Fnd ½" Rerod in a Monument Box (A-8) B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1998-Kennedy Surveying, Inc. – Kennedy, PS #17623 - The comer was recovered based upon the State Plane Coordinates provided by JCK & Associates, Inc. The comer as recovered is located 10 feet West of the existing centerline of Inkster Road extending to the North & South, which has a bituminous surface, and 7.00 feet North of the existing centerline of Lone Plne Road extending to the East, which has a bituminous surface. The West ¼ comer of Section 19, T2N, R10E, Bloomfield Township (M-8) is located 6.77 feet to the South. 				
	FIELD MEASURME			70	
	M-8 to A-8 No GLO 6.77 Ft. (M)	M-8 to M-7 GLO = 40 chains or 2640.00 Ft. No plat or sidwell distances 2728.48 Ft. (GPS-MEA)	M-8 to M-9 GLO = 40 chains or 2640.00 No plat or sidwell distances Survey recorded in L. 6898, p 2736.34 Ft. (GPS-MEA)	og.796 = 2731.02 pt. 60.77 Ft. 2737.7 Ft. HUSTON	
C.	Description of monument for corner and accessories established to perpetuate locating the position of the corner PROFESSIONAL M-8 I set a 5/8" x 24" Iron Rod w/2" diameter brass cap stamped Oakland County Remonument For PS WAR Sin A set Monument Box S65°E 115.61' Set Mag Nail & Remon Washer NE face Power Pole N85°E 77.40' Cut "x" top bolt on Fire Hydrant N40°W 38.18' Set Mag Nail & Remon Washer NE face 10" Box Elder				
		S'E 115.61' Set Mag Nall & Remon Washer NE face Power Pole			
	N65°E 77.40' Cut "x" top bolt on Fire Hydrant				
	S22°W 60.17' Set #	Mag Nail & Remon Washer NE f Mag Nail & Remon Washer SE fi st ¼ comer Section 19, T2N, R1	ace Power Pole		
The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.					
Signed by: 10-9-98					
•	veyor's Michignan Lice	ense No. 17623			
FORM APPROVED BY MICHIGAN CTATE BOARD OF PROFESCIONAL CUM/EVORS 1AN 25 467					