

MAR 04 1998

## SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970Compliance with  
ACT 345, P.A. 1990

For corners in

Oakland  
(County)Located in: City  
of Troy

Corner Code #

1. Public Land Survey T 2N R 11E A-2  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_
2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_
3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

APPROVED ON: 4-9-97 JS  
OAKLAND COUNTY REMONUMENTATION  
PEER GROUP COMMITTEE

\$ 7.00 MISCELLANEOUS RECORDING  
\$ 2.00 REMONUMENTATION  
9 JUN 97 12:18 P.M. RECEIPT# 94A  
PAID RECORDED - OAKLAND COUNTY  
LYNN D. ALLEN, CLERK/REGISTER OF DEEDS  
Register of Deeds Stamp & File Number

I, Randy Kolehhouse, in a field survey on March 19 19 97,  
do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

**NOTE:** Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-2 This corner was not originally set by the G.L.O.

1954	McAlpine	Charnwood Hills No. 1 L. 71 P. 7	N/A
1954	N/A	Charnwood Hills No. 2 L. 73 P. 21	N/A
1987	Donnelly	Tall Oaks Sub. L. 203 P. 17	N/A
1987	Donnelly	L.C.R.C. L. 11270 P. 301	PK Nail
1993	Wilkerson	Unrecorded L.C.R.C.	PK Nail
N/A	N/A	O.C. Section Information	N/A
N/A	N/A	O.C. Tax Maps	N/A

Records indicate this corner is common with M-2, T2N, R10E.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-2 Reset point using witnesses found per L.C.R.C. L. 11270 P. 301 and an unrecorded L.C.R.C. by Wilkerson. This point was  
established by R. Donnelly in 1987 using recorded plat information per L.C.R.C. L. 11270 P. 301. Checks Charnwood Hills No. 1  
and No. 2. Also checks Tall Oaks Sub.

L.C.R.C. L. 11270 P. 301 (1987)	Unrecorded L.C.R.C. (1993)
Az 162° 114.02' PK Nail West Face 20" Maple	S 15° E 114.10' PK w/Washer
Az 210° 91.20' PK Nail West Face Light Pole	S 34° W 91.20' PK w/Washer W Face L. Pole
	N 82° W 46.95' Nail w/MSHD Tag

Measure North 3205.8' to A-1 (G.L.O. = 3366.0') (Tall Oaks Sub. = 3205.63')

Measure South 2663.5' to A-3 (G.L.O. = 2640.0') (Charnwood Hills No. 1 = 2663.4') (Charnwood Hills No. 2 = 2663.77')

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-2 Replaced the capped rebar with a 5/8" x 24" rebar with brass cap stamped "Oakland County Remonumentation P.S. #25854." Also  
set a new monument box.

PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in West Side 20" Maple S 15° E 114.10'  
PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in West Side L. Pole S 34° W 91.20'  
PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in 15" Tree N 82° W 46.95'  
PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in NW Side 24" Maple N 40° E 66.4'

The selected location is accepted by the Contractor and is generally accepted by professional  
surveyors as the best available evidence of the position of the original corner.

Signed by

Randy J. Kolehhouse  
EARTH TECH

Date

5/28/97

Surveyor's Michigan License No.

25854