

SURVEY & REMONUMENTATION

MAY 24 2000

LIBR 20934 252

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oakland

(County)

Located In:

Highland Township

Corner Code #

1. Public Land Survey

T3N R7E L-7

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. Recorded Plat

5. Private Claims

I, Huston K. Kennedy, in a field survey on October 4, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1817-GLO Wampler, D.S.; Set Post 18" White Oak N30°E 3.10 chains; 20" White Oak S77°W 4.29 chains
- 1.) 1976-Hooth, PS #7966; LCRC L.6770, pg.867 - Fnd a Monument in a Monument Box
- 2.) 1991-Owens, PS #20709; LCRC L.11781, pg.003 - Fnd a Re-rod in a Monument Box
- 3.) 1993-Thompson, PS #23828; LCRC L.13481, pg.182 - Fnd a 1/2" Iron in a Monument Box, no witnesses
- 4.) 1962-Oakland County Road Commission unrecorded witnesses - Fnd a 4" diameter Concrete Monument
- 5.) M.DOT Right of Way Map - Object found not stated, no witnesses (Con't on back side)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1999-Kennedy Surveying, Inc. - Kennedy, PS #17623 - Fnd a 1/2" Iron Rod in a Monument Box located in the existing centerline of M-59 Highway extending to the East & West, which has a bituminous surface, also located in the centerline of Duck Lake Road extending to the North & South, which has a bituminous surface.

Witnesses from LCRC #2 & local monumentation were used to recover and verify the location of the found 1/2" Iron Rod in a Monument Box.

I accepted the found 1/2" Iron Rod in a Monument Box as the best evidence of the original corner position.

Field measurements see back side

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- L-7 I replaced the found 1/2" Iron Rod with a 5/8" x 24" Iron Rod w/2" diameter brass cap stamped
- Remonumentation, PS #17623 in an existing Monument Box
- N46°E 80.29' Set Mag Nail & Remon Washer NW face Guide Pole
- N47°W 92.21' SE corner of building #2887
- S47°W 162.88' Cut on top of North nut on traffic pole
- S43°E 169.14' NW corner of building #2920

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by: Huston K. Kennedy

Date 11-26-99

Surveyor's Michigan License No. 17623

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYOR'S, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

457113

LIBR 20934 PAGE 252
\$9.00 MISC RECORDING
\$2.00 REMONUMENTATION
10/29/1999 02:41:01 P.M. RECEIPT# 110737
PAID RECORDED - OAKLAND COUNTY
G. WILLIAM CADDELL, CLERK/REGISTER OF DEEDS

Compliance with
ACT 345, P.A. 1990

APPROVED ON: 11-24-99 JH
OAKLAND COUNTY REMONUMENTATION
FILE # 11-24-99

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

