LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	12.
1. PUBLIC LAND SURVEY	_ T. 3 N; R. 9 E	_3-5	1 24 A- 1" -
2. PROPERTY CONTROLL-	,T. 3, R. 2 E.	B-5	
3. MISCELLANEOUS PROPERTY IN SECTION			
4. LOT NO , RECO	ORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on Additional 1923, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on August 16 1923, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:			
A. Description of original monument and accessories and/or subsequent restoration:			
B. Danasiasian of garage suide	nce found and/or method and	olied in restoring or rejectab	lishing corner:
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:			
RESOURE-1	13 Tean Fre	, .	
IN Hole IN PAYE & GALC ROAR			
C. Description of monument f	or corner and accessories e	stablished to perpetuate loca	ating the position of the corner:
L' JRON 10	" A GAR FOAL"		
11. 33° W. 45			
N. 52° E, 53			
S, 40° W. 73			
N. 02° E. 33.	_		
SIGNED BY	WALLS IN SOUR FOR	•	
SURVEYOR'S MICHIGAN REC	GISTRATION NO		(SEAL)
FOR STATE AND UNITED ST			
SIGNED BY	CHIEF OF SURVEY PARTY	DATE	
	missioni nevisienev ka		(SEAL)