

SURVEY &  
REMONUMENTATION

MAR 14 95 041386

LIBER 15290 PG 572

MAY - 1 1995

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

OK - T. SMITH

For corners in  
OAKLAND  
(County)

COMMISSION

Located In: WATERFORD Corner Code #

1. Public Land Survey T 3 N R 9 E E-8  
T R  
T R  
T R  
T R
2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Sec. S T R

\$ 7.00 HISC RECORDING CHG - IN HOUSE  
\$ 2.00 REMON CHG - IN HOUSE  
14 MAR 95 9:14 A.M. RECEIPT# 45B  
PAID RECORDED - OAKLAND COUNTY  
LYNN D. ALLEN, CLERK  
REGISTER OF DEEDS  
ACT 345, P.A. 1990

APPROVED ON: 12-30-94  
OAKLAND COUNTY REMONUMENTATION  
PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat  
5. Private Claims

I, THOMAS M. SMITH, in a field survey on NOVEMBER 29, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

POST, G.L.O.	1/2" IRON ROD	1/2" ROD IN 3/4" PIPE	1/2" IRON IN 3/4" PIPE
1817	ROAD COMMISSION	L.C.R.C.	L.C.R.C.
1963		L. 7400 P. 316	L. 8364 P. 661
		HOOTH, 1978	J. SMITH 1983

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I FOUND A MDOT DISK ON A ROD INSIDE A PIPE IN A MONUMENT BOX AT THE INTERSECTION OF PONTIAC LAKE ROAD & AIRPORT ROAD. I VERIFIED THE CORNER POSITION BY THE RECORDED L.C.R.C.'S AND BY THE TIE NORTHWESTERLY TO THE SCHOOL BUILDING. ALSO THIS CORNER FITS WITH THE PLAT OF HIGHLAND ESTATES. MEASURED DISTANCES NORTH VERIFY THE CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-8: I REPLACED THE MDOT BRASS DISC WITH A 5/8" ROD WITH BRASS REMON CAP #31606  
N 45 E. 87.30' to remon tag S.E. side 12" ash.  
S 45 W. 65.95' to remon tag N. side 12" pine.  
N 30 W. 53.45' to capped iron.  
N 45 W. 161.25' to S.E. corner school building.

THE SELECTED LOCATION IS ACCEPTED BY ME AND IS GENERALLY ACCEPTED BY PROFESSIONAL SURVEYORS AS THE AVAILABLE EVIDENCE OF THE ORIGINAL CORNER.

Signed by *T. Smith*

Date DECEMBER 19, 1994

Surveyor's Michigan License No. 31606

7.00  
2.00  
T.h. chg

