MAY 24 2000

SECTION

LIBER 21119 - 599

51686 LAND CORNER RECORDATION CERTIFICATE 21119 PAGE Filing Regulrement of Act 74, Mich. P.A. 1970 \$9.00 MISC RECORDING \$2.00 REMONMENTATION 02/18/2000 02:36:27 P.M. RECEIPT# 14203 PAID RECORDED - OAKLAND COUNTY G. WILLIAM CADDELL, CLERK/REGISTER OF DE For corners in Corner Code # Located in: Oakland Waterford Township (county) R9E Crista (1.4. 1998) ACT 304 (1.4. 1998) 1. Public Land Survey 12-15 99 371 CELARD COUNTY DEMORST TO CELE GRIEF TO CONTRACT TO 2. Property Controlling S PEER GRIEF in Section Register of Deeds Stamp & File Number 3. Miscellaneous Property in Sec. 4. Lot No. . Recorded Plat 5. Private Claims i, <u>Joseph C. Kapelczak</u>, in a field survey on <u>April 13, 1999</u>, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey s instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 10 A. Description of original monument and accessories and/or subsequent restoration: 11 12 Set post in 1816 G.L.O. Survey. There is one LCRC recorded at Oakland County; Kapelczak 1991. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Recovered concrete monument at this location, per plat of Waterford Meadows Subdivision as recorded in L 184 P 18. This location was validated with monumentation found in Waterford Meadows Subdivision #1 and Pilgrim Hills Subdivision No. 2. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set Oakland County Remonumentation Brass Cap stamped #24598 on existing concrete monument.

*N 87°E 25.71' PK nail with OCRT #31606 south side 24" Cherry. S 30°E 12.36' PK nail with OCRT #31606 west side 32" Cherry.

N 8°W 10.40' PK nail with OCRT #31606 east side 12" Pine.

N 30°W 29.28' Mag nail with OCRT #24598 east side 12" Pine.

*Reused Recovered Witness

Wh



Signed by C. Kake Look
Surveyor's Michigan License No. 24598

Date /2/22/99