

# SURVEY & REMONUMENTATION

LIBER 14833 PG 134

94 193378

MAY - 1 1995

## COMMISSION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
Oakland

(County)

Located In:

Corner Code #

OK - T. SMITH

1. Public Land Survey

5N 11E

G-3

T R

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

\$ 7.00 MISCELLANEOUS RECORDING

\$ 2.00 REMONUMENTATION

15 JUL 94 7:30 A.M. RECEIPT# 1A

PAID RECORDED - OAKLAND COUNTY

LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

APPROVED ON: 12-22-93

OAKLAND COUNTY REMONUMENTATION

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

Bruce Antcliff

November 9

93

I, in a field survey on 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

G-3

GLO  
Post

County Witness

Stone

SW - 102.5' 8" Oak

NE - 139.6' 18" Elm

SSW - 105.5' 18" Oak

L.C.R.C. L.8846, P. 262 (1984)

3/8" Iron Rod & Steel Fence Post

S 10° E - 73.97' N/W, NE Face 21" Oak

S 45° W - 45.03' N/W, NW Face P. Pole

S 70° E - 63.22' N/W, S Face 12" Oak

N 05° W - 12.07' N/W, S Face 12" Oak

L.C.R.C. L. 6717, P. 294 (1976)

3/8" Iron & Steel Fence Post

S 10° W - 19.00' 5" Ash

N 70° W - 13.45' 5" Poplar

N 80° E - 11.40' 10" Oak

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-3 Found 3/8" Iron pin 50' N of curve in Haven Road. Marked with steel fence post.

Checks the following witnesses:

L.C.R.C. L. 8846, P. 262

S 10° E - 73.97' Nail NE Side 21" Oak

S 45° W - 45.03' Nail NW Side P. Pole

S 70° E - 63.22' Nail S Side 12" Oak

Also checks Witness from

surveys by Thomas M. Smith &

Glen J. Heil.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-3 The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

Set concrete monument with standard Oakland County cap.

P.K. Nail and Brass Tag in E Face Power Pole - S 45° W - 45.10'

P.K. Nail and Brass Tag in N Face 14" Oak - S 70° E - 63.26'

P.K. Nail and Brass Tag in W Face 10" Poplar - N 40° W - 13.23'

P.K. Nail and Brass Tag in SW Face 12" Oak - S 40° E - 63.38'



Signed by Bruce Antcliff

Date 7-11-94

Surveyor's Michigan License No. 25826