

MAY 1 6 18:97

SINGERON WAR COUNTY OF THE RECEIVED FOR REDOC

100683

COMMESSAGE LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

'96 DEC 19 Att :11

| For corners in | Timig Hequit | entent of Act 14, Mich. 1. | A. 1010 | OLO 12 Mil 111 | |
|--|--|--|--------------------------|--|-------------|
| Oceana | Located In: | Corner Code # | | | |
| (County) | _ | | Jung. | رين جي المراجعة المر المراجعة المراجعة ال | ř |
| 1. Public Land Survey | T <u>14N</u> R <u>15</u> V T R | ······································ | · | NOTER OF DECUS. | |
| O. Disaments Continuitions | T R T R S T R | | | | |
| Property Controlling in Section | S T R | | | | |
| 3. Miscellaneous | S T R | | | | |
| Property in Section | S T R | | Register of I | Deeds Stamp & File | Number |
| 4. Lot No Rec | corded Plat | | | | |
| 5. Private Claims | | | | | 1111 |
| | | | 2 6- | | |
| | | | 3 | | |
| | | | 4 | | 12- |
| _{I,} J. Randolph Hepworth, ii | n a field survey onJt | ine 3 , 19 <u>96</u> | , 5 | | |
| do hereby certify that under requi | rements of P.A. 74, Michigan P. | A. of 1970, the corner points men | ntioned 6 18 | 15- | 14-13- |
| | | rules therefore as required in the conent of the Interior, Bureau of | | | |
| | | orner points mentioned in lines 3, | | 1202122- | 23 - 24 |
| | | Soard of Professional Surveyors o | | | |
| | shed, re-established, monumer | nted, re-monumented, recovered, | | | |
| as expressed below: | | | 10 30 L | 29 28 27 | 2625- |
| NOTE: Not more than 4 corn | ers, all in the same town and | d range, may be recorded | 11 | | |
| on this certificate. | | • | 12 -31 | 32 33 34 | 35 - 36 - |
| A Description of original m | anyment and acceptant | | 13 | | |
| | | and/or subsequent restoration T14N, R15W Newfield To | arran la la | cana County Remonu | |
| GLO SET POST 10 |)"Beech S16°W 21.1' | 8"Beech N57°W 21 | 1486 | er Group Ravinuad e. | A |
| | | | Dat | te: 11-7-96 | 145010460 |
| Book A, Pg 578; H.C.Hawley, 1 | 883, Hole of 3' deep by 3 1/4" i | n dia. filled with charcoal, broken b | orion, organory, sto. | | 0-11- |
| Book C, Pg 2; F. Wetmore, 19 | S16°W 21.1' | 24" Hemlock N11°W 19 y Hawley in margin of lake, no brid | 3.8' — ok.¤ J. £i | Randolph Hapworth | -21 |
| Book B, pg 8, F. Wetmore, 19 Book C, Pg 74; H. Salisbury, | 00; "Old qu. post set by Haw | vley. See Co Record," | Oce | eana County Surveyor | |
| OCRC WITNESS BOOK 1976 12"-12" Tw. R. Oak | | "-14"-14"Tri. R. Oak S75°E 46.6 | (A' 16'1\) | Oak S80°W 22.06' | |
| | | | 1044. | , | |
| 12"-12" Tw. R. Oak S35°E 54 | 439 12-23-75 Fnd. Brick & Se 1.73' 8"-14"-14"Ti | et Conc Mon ri. R. Oak S75°E 46.64' | 16"W. Oak \$80° | 'W 22.06' | |
| P.A. 132 Survey Jacket # 174 P.A. 132 Survey Jacket # 328 | | 12-4-75 same as LCRC 3-5-82 Fnd Conc Mon, Jkt 174, | 100189 Sheet 2 of 6 | | |
| R. Hepworth PS 26457 Unrec 12" tw R. Oak S35°B | orded Survey 3-28-86 Fnd Co 5 54.73' 14" tr R. Oa | onc Mon at Fence Cor. k S75°E 46.64' | 16" W. Oak S80 | °W 22.06' | |
| B. Description of corner e | :vidence found and/or met | thod applied in restoring or r | reestablishing corn | ıer. | |
| I found a 4" dia. concrete monu | ment with 1/2" Iron projecting 0 | .5' above ground and 0.9' west of a | a 5' tall 1-1/4" Pipe gu | ard post. Trace of old | fences |

east-west & north. Found pieces of brick beside the monument at the surface. N. Ochs stated that he found brick which is presumably the Hawley, 1883 corner. All Ochs, 1975, witnesses are standing and measure good.

This concrete monument was accepted as the best evidence of the corner and was accepted as being a careful and faithful perpetuation of the original corner. No evidence is known to me that would lead me to believe that the corner should be in another location. The monument is a substantial marker and was accepted as found. I did not replace with a Harrison monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

| F-7 | 1/4 Corner Cor | mmon to Sections 16 & 21 | T14N, R15W | Newfiel | d Township | E of MICH |
|--|---|---|---|--|--|--|
| 4" dia. C | oncrete Monum | ent | | | | |
| 60d spk 60d spk 60d spk 60d spk | N Face NW Face N Face NW Face NE Face E Face | 24" W Oak 6" R Oak 16" R Oak 10" W Oak tw Oak Stump 12" tw R Oak | \$80°W N15°E \$85°E \$30°W \$35°E \$25°E | 22,07 13.75 46.00 39.44 54.55 69.33 | TAPE TAPE TAPE TAPE TAPE TAPE | RANDOLPH HEPWORTH LAND SURVEYOR NO. 28457 |
| Signed by | 1 than | John Agua | Æ. | | _ Date | December 5, 1996 |

Surveyor's Michigan License No. 26457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED NAY 14, 1975 REVISED JAN., 1983