

SURVEY & REMONUMENTATION

OCT 27 1993

COMMISSION

OCEANA COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN  
COUNTY OF OCEANA  
RECEIVED FOR RECORD  
1005  
'93 OCT -7 P2:45

*James E. Martin*  
REGISTER OF DEEDS

For corners in

<u>OCEANA</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>15N</u> R <u>18W</u>	<u>D-7</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous	S _____ T _____ R _____	_____
Property in Sec.	S _____ T _____ R _____	_____

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L
2	6	5	4	3	2							
3												
4	7	8	9	10	11							
5												
6	18	17	16	15	14							
7												
8	19	20	21	22	23							
9												
10	30	29	28	27	26							
11												
12	31	32	33	34	35							
13												

I, J. Randolph Hepworth, in a field survey on September 27, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A. D-7 1/4 CORNER COMMON TO 17 & 20 GOLDEN TOWNSHIP; T15N, R18W  
GLO SET POST 12" PINE N04°E 11.2' 12" W OAK S31°W 9.9'  
BOOK A- 228 RM HYDE, APRIL, 1889 SET POST FROM OLD WITNESS TREE STUMPS  
OCRC WITNESSES: 10-4-73 IRON  
14" W PINE S77°E 51.18 6" W CHERRY N04°W 27.80 20" W OAK N84°W 23.40  
OCRC WITNESSES: OLDER, NOT DATED IRON  
16" OAK NW 25.50 4" PINE E 51.38 16" OAK FACE ENE 33  
FENCE POST E 31.0 16" PINE-FACE SSE 58.25  
6" PINE NW 8.1 20" OAK WSW 37.4  
PLAT 02- 'LAKE HOLIDAY GARDENS'  
UPPER SILVER LAKE PLAT NO. 10  
OCRC WITNESSES PRIOR TO NEW ROAD CONSTRUCTION: TAKEN BY HEPWORTH DEC. 1988  
FOUND 3/4" PIPE  
FD 1/2" IRON, PVK 8618 SOUTH 31.86' PLAT CORNER  
16" W OAK N74°E 34.10 (GONE 8-93) 14" W PINE S68°E 58.49 (OK-8-93)  
16" TW R OAK S68°W 38.67 (OK-8-93) CONC MON SE 46.17 (GONE 8-93)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner

FOUND 3/4" PIPE, 2' BELOW PAVEMENT AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

D-7 1/4 CORNER COMMON TO 17 & 20 GOLDEN TOWNSHIP; T15N, R18W  
SET "COUNTY SURVEYOR" HARRISON 4"x20" CAST IRON MONUMENT OVER THE TOP OF THE FOUND 3/4" PIPE.  
60d SPK S FACE 12" W PINE S86°W 74.21 EDM  
60d SPK NW FACE 36" TW OAK S66°W 38.67 EDM  
60d SPK N FACE 12" W PINE S70°E 58.49 EDM  
60d SPK N FACE 16" W PINE N74°E 51.87 EDM  
60d SPK NW FACE 10" W PINE N42°E 55.25 EDM  
CENTER N-S PAVEMENT

Signed by J. Randolph Hepworth  
Surveyor's Michigan License No. 26457



Date September 30, 1993

11-5-93