

JAN 18 2001

## SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970STATE OF MICHIGAN  
COUNTY OF OCEANA  
RECEIVED FOR RECORD

21 DEC 2000 3:10:55 PM

JOSEPH E. MERTEN  
REGISTER OF DEEDS

100987

Register of Deeds Stamp &amp; File Number

For corners in

Oceana

(County)

Located In:

Corner Code #

1. Public Land Survey

	16N	16W	G-8
T	R		
T	R		
T	R		
T	R		
T	R		

2. Property Controlling  
in Section

S	T	R	
S	T	R	
S	T	R	
S	T	R	

3. Miscellaneous  
Property in Sec.

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

J. Randolph Hepworth, in a field survey on June 7, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

## A. Description of original monument and accessories and/or subsequent restoration:

G-8 1/4 CORNER COMMON TO SECTIONS 21 &amp; 22 T16N, R16W

CRYSTAL TOWNSHIP

GLO J. Hodgson 1838 SET POST 12" Beech N15°E 6 lks 8" Beech S34°W 22 lks  
Book A, Pg.268, H.A.Grant, 1887; Sec 22,T16N,R16W "Found iron rod recognized as Gov't Cor."

OCRC Witness Book 1960 Axle set in place of Wood stake in pocket of stone & crockery  
1) 36" Maple N40°W 58.3' 2) 18" Twin Ash S45°E 59.7'

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.


I found an automobile rear axle shaft with 4" gear on its end in the centerline of N-S gravel road and on old occupation line to the west. No occupation is visible to the east. On excavation, I found a nearly complete brown crockery jug all broken up and four 12" dia. Stones. I also found the axle to be in the center of the stones and immediately beside a 1/4"x1 1/4" bar. I did not find any wood fragments. Witness #1 is standing and measures OK; witness #2 is missing. I believe this to be the Grant, 1887. monument with the axle shaft added by OCRC.

I accept the axle shaft Iron and other material as the best available evidence of the position of the original corner. No evidence is known to me that would lead me to believe the corner should be at another location.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 4"x20" Harrison Cast Iron Monument, stamped "County Surveyor" and "26457" above the axle shaft and bar which were driven down. The stones were discarded and the crockery pieces placed around the monument.

Set 60d spk	NW Face	3" Fir	33°az	46.56'	EDM
1) 60d spk	SW Face	48" Maple	322°az	59.32'	EDM
set 60d spk	N Face	12" Poplar	273°az	94.75'	EDM
Fd 1/2" Iron/cap	LS12016		271°az	33.02'	EDM
Set 60d spk	E Face	10" Ash	190°az	67.72'	EDM

Oceana County Re-monumentation  
Filer Group Reviewed & Approved

Date: 11-21-00

J. Randolph Hepworth  
Oceana County SurveyorSigned by J. Randolph Hepworth  
Surveyor's Michigan License No. 26457Date December 15, 2000