

SURVEY &
REMONUMENTATION

JUL 23 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Ogemaw
(County)

Located In:

Corner Code #

1. Public Land Survey T R
T R
T R
T R
2. Property Controlling S 13 T 21N R 1E MC on N. side
In Section S T R Lake George
3. Miscellaneous S T R
Property In Sec. S T R

4. Lot No. , Recorded Plat
5. Private Claims

LIBER 3 PAGE 24

STATE OF MICHIGAN
OGEMAW COUNTY
RECORDED

28 DEC 95 3:21 P.M.

WANDA HUZIK
REGISTER OF DEEDS
Register of Deeds Stamp & File Number

I, Timothy L. Lapham a field surveyor on December, 19 95,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO Clason 1838, Set Post for Meander Corner;
Unrecorded Survey, Henning 1942, No Cor Mat, No Wits;
Unrecorded Survey, Richardson, No Date, No Cor Mat, No Wits;
Plat, Richardson, Springhill Subdivision (Rec 3-20, 12/22/58), No Cor Mat, 2 Wits

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of GLO survey found. Corner not Found. Restablished corner position from
Springhill Subdivision. Matches Richardson and Henning Survey, with position falling in
Lake. Set Reference corner on North shore of George Lake 29.72' North of platted Meander
corner position on Township line. Accepted platted position as best evidence of the
accepted corner position with monumented position 29.72 feet north of position. See
dossier for additional information.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8"X36" rerod with 3-1/4" Aluminum Ogemaw Remon cap marked "27595 1995" for refer
to M. C. position 29.72' north thereof along Township line.

From Which:

N04E 30.00' PK nail in Centerline Pavement
S75E 20.91' 10" Elm with nail
South 12.26' Waters edge
S86W 34.68' End post of North-South Fence with nail
N14W 1.22' Centerpost of Guard Rail with nail

Signed by

Date

Surveyor's Michigan License No. 27595