

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:  
Ogemaw  
(County)

Located In

Corner Code #

1. Public Land Survey T 21N R 3E B-3  
T R  
2. Property Controlling in Section S 6 T 21N R 3E 10  
S T R  
3. Miscellaneous Property in Section S T R  
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on February 7, 2006 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3	7	8	9	10	11	12							
4													
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

B-3 G.L.O. J. Mullet July 1846 set quarter section post  
Wit: W. Pine 30" N72°E 77 links  
W. Pine 30" S45°E 87 links

10-This corner position was not established during the original government survey.

Sept. 1970 Norman Parker R.L.S. #16939 set a 1/2" x 18" bar by proportionate distance East & West.

Wit: 24" W. Pine S29°E 61.0'  
7" B.Oak N25°E 26.0'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

B-3 Found 1/2" rod fitting N. Parker's survey in section 6 and accepted by local surveyors for a considerable amount of work in sections 6&7. Distance East fits G.L.O. distance reasonably well distance West is 56' longer than recorded G.L.O. distance.

10- Established the Northwest corner of the Southwest quarter of the Southwest quarter of section 6 as per B.L.M. instructions for the subdivision of a section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-3 Found 1/2" rod added P.S. cap #33981

Wit: 10" Oak S30°E 22.82'  
10" Oak S31°W 17.55'  
13" Oak N65°W 52.45'  
Wooden Post N03°E 8.50'  
9" Oak N53°E 25.35'  
Carsonite Post South 15'±

10- Set P.K.nail

Wit: Well Point S86°W 73.23'  
14" Twin Oak S46°W 64.75'  
5" W. Pine S55°E 56.87'  
9" Oak N75°E 85.89'  
Carsonite Post East 50'±  
Centerline of M-33 East 2.8'±

Signed by:

Carl T Kiiskila

Date:

2/13/06

Surveyor's Michigan License No.:

33981

