

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Ogemaw
(County)

Located In

Corner Code #

1. Public Land Survey T R
T R
2. Property Controlling in Section S 8 T 21N R 3E 15
S T R
3. Miscellaneous Property in Section S T R
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on June 3, 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

15 - W 1/16 Corner common to sec.'s 8 & 17, T21N, R3E

1974 - Cert. of Survey - L.2, p.15 - Norman C. Caldwell, P.S.#12018 - Shows corner on survey. Shows distances to East and West.

1974 - Corner References - L.2, p.16 - Norman C. Caldwell, P.S.#12018 - Set 1/2" Bar. Placed DNR post alongside. S21°W 31.5' 8" Triple Oak S23°E 45.3' 10" Twin Oak

1974 - L.C.R.C. - L.1, p.69 - Norman C. Caldwell, P.S.#12018 - Same info as L.2, p.16.

1976 - Cert. of Survey - L.2, p.147 - Robert L. Higgins, P.S.#21570 - W 1/8 corner of secs. 17 & 8, T21N,R3E, fd. 1/2" bar.

1976 - Cert. of Survey - L.2, p.138 - Robert L. Higgins, P.S.#21570 - W 1/8 corner of secs. 17 & 8, T21N,R3E, fd. 1/2" bar of record

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

15 - W 1/16 Corner common to sec.'s 8 & 17, T21N, R3E

Found 1/2"x18" rebar without RLS cap in Red Pine plantation. Cedar guard post was down and destroyed. Placed P.S. cap #33981 on found rebar. Accepted found 1/2"x18" rebar as the best available evidence for the position of the corner. Found no other evidence to dispute this location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

15 - W 1/16 Corner common to sec.'s 8 & 17, T21N, R3E

1/2"x18" rebar with P.S. cap #33981

Wit: N45°E 24.54' to set N&T on NW side 6" R.Pine
S37°E 46.22' to set N&T on NE side 14&16" Twin Oak
S17°W 31.83' to set N&T on NW side 12" Twin Oak
N54°W 11.61' to set N&T on NE side 7" R.Pine
Set Blue Carsonite Post w/ location tag 1' North



Signed by:

Carl T Kiiskila

Date:

8-13-09

Surveyor's Michigan License No.:

33981