

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:  
Ogemaw  
(County)

Located In

Corner Code #

1. Public Land Survey	T	23N	R	1E	A-2
	T	23N	R	1E	A-3
2. Property Controlling in Section	S	T		R	
	S	T		R	
3. Miscellaneous Property in Section	S	T		R	
	S	T		R	

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Carl T. Kiiskila, in a field survey on January 12, 2006 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

A-2 G.L.O. Lewis Clason 1838 set quarter section post

Wit: Spruce Pine 5" S13°E 70 links  
Spruce Pine 6" N22°E 1.54 chains

A-3 G.L.O. Lewis Clason 1838 set corner for sections 6 and 7.

Wit: Spruce Pine 4" S76°E 25 links  
Spruce Pine 4" N50°E 57 links

Marcus Schaaf R.L.S. #3104 index indicates he used this corner circa 1940 to set the center of section 6. Type of monument and witnesses not given.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

A-2 Found a 4" pipe near the intersection of fire lanes North, South, and East. The pipe was leaning over possibly hit by planting equipment. Set a standard DNR monument at the base of found 4" Pipe

A-3 Found a 4" pipe with a brass cap similar to the monument found at the center of section 6 set by Marcus Schaaf R.L.S. #3104 circa 1940.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-2 Set 1" X 32" pipe with standard DNR cap.

Wit: 10" J. Pine N53°W 60.57'  
6" J. Pine N84°E 65.39'  
5" J. Pine S38°E 23.92'  
6" J. Pine S46°W 82.55'  
Blue Carsonite Post North 1'±

A-3 Found a 4" pipe with a brass cap in concrete.

Wit: 10" J. Pine S28°W 5.40'  
5" J. Pine N01°E 13.41'  
5" J. Pine N63°E 21.27'  
8" J. Pine S72°E 25.34'  
Blue Carsonite Post North 1'±

Signed by:

Carl T. Kiiskila

Date:

1-31-06

Surveyor's Michigan License No.:

33981

