

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Ogemaw

(County)

Located In

Corner Code #

1. Public Land Survey		T	23N	R	2E	A-12
		T		R		
2. Property Controlling in Section	S 31	T	23N	R	2E	3
	S	T		R		
3. Miscellaneous Property in Section	S	T		R		
	S	T		R		

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on January, 2000 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

A-12 GLO James H. Mullett D.S. 1846
Set quarter section post
No witness trees

3-This corner position was not established during the original government survey.

Larry L. Cavanagh LS#17614 Plat of "Ogemaw Hill Estates" shows East 1/4 corner section 36 T.23N., R.1E. No description of monument given.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

A-12 Found and accepted 1/2" capped rod L.S. #17164

3- Established the Northwest corner of the Southwest quarter of the Northwest quarter of section 31 per B.L.M. instructions for the subdivision of a section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-12 Found 1/2" capped iron #17614

Wit: 9" Oak	S38°W	15.86'
10" Oak	N67°W	26.48'
3" Maple	N72°E	20.25'
8" Maple	S54°E	20.57'
Carsonite post	North	1'±

3- Set 5/8" X 32" rerod with P.S. cap #33981

Wit: 16" Oak	S54°W	3.98'
10" Oak	N28°W	17.24'
8" Oak	N44°E	16.28'
5" Maple	S23°E	6.40'
Carsonite Post	North	1'±

Signed by:

Carl T. Kiiskila

Date:

8-30-01

Surveyor's Michigan License No.:

33981

