

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
OGEMAW

(County)

Located In:

Corner Code #

1. Public Land Survey

T 21N R 2E  
T R  
T R  
T R

E-11, F-11,  
F-13

2. Property Controlling  
in Section

S T R  
S T R

3. Miscellaneous  
Property in Sec.

S 32 T R  
S T R

1653.72' E OF  
D-11.

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, CARL F. ROSER, in a field survey on AUGUST 25, 19 93,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-11

F-11

F-13

(NO EVIDENCE OF G.L.O. CORNER, B.T.'S, LINE TREES & TOPOGRAPHY,  
AS CALLED OUT IN THE G.L.O. LINE NOTES; UNLESS NOTED IN ITEM "B"  
BELOW.)

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-11

F-11

F-13

FD R.R. SPK OVER STRONG DIP  
FOR NE COR S-32. P.S. D.L.E.DY  
SAYS SET R.R. SPIKE IN 1985  
CERT OF SURVEY IN SE 1/4 OF  
S-29. COR ALSO FITS P.S.  
R.HIGGINS 1982 CERT OF SURVEY  
IN SE 1/4 OF S-29. CTR OF E-W  
B.TOP IS 2.4' SOUTH.

FD 1/2" REROD 1' NORTH OF CTR  
E-W B.TOP RD FOR N 1/4 COR  
S-33. COR IS IN LINE W/FN TO  
NORTH. CTR OF GRAVEL RD SOUTH  
IS 42'± E. COR FITS SURVEY BY  
L. CAVANAGH, 1972, IN S-33.

FD PIPE FOR S 1/4 SEC 33. OLD  
WORKING DRAWING FROM  
L.CAVANAGH (NDRSTAR SUR & ENGR  
ALSO HAS COPY) SAYS "FD 1 1/2"  
PIPE, ORIG WIT STUMP". NE FD  
MOSS COVERED HUMP NO3 W,  
12 1/2"; US = HEM 6 IN NO2 W,  
12.5'. PIPE ALSO FITS US TIE  
TO "BROOK 5 LKS" 660' EAST  
EXACT.

ESTABLISHED NW COR OF E 1/2 OF  
NW 1/4 OF NE 1/4 OF S-32 PER  
STANDARD BLM INSTRUCTIONS.  
COR FALLS IN CTR E-W B.TOP RD.  
E-W ROW FN (B/WIRE ON WOOD AND  
STEEL POSTS) IS 41' NORTH.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-11

F-11

F-13

FD RR SPK. REPLACED WITH  
5/8" x 3/4" REROD W/RLS CAP.  
11" POWER POLE N05°E 34.91'  
11" SCOTCH PINE N50°W 70.05'  
11" RRR TIE POST S05°E 35.00'  
CTR GR RD N'LY WEST 22'  
SET CED POST WITH  
LOC TAG SOUTH 33'  
11" RLS D. LEDY WIT.  
11" RLS HIGGINS WIT.

FD 1/2" REROD, RAISED WITH  
3/4" x 23" GALV PIPE.  
11" SPRUCE N10°W 47.48'  
11" POWER POLE N65°E 67.76'  
11" R PINE SOUTH 59.03'  
11" SCOTCH PINE S40°W 60.95'

FD 1 1/2" x 49" BLACK IRON  
PIPE.  
10" W PINE N65°W 33.12'  
11" MAPLE N20°W 19.64'  
9" MAPLE N15°E 30.26'  
9" BALSAM N42°E 13.10'  
N 1/4 S-2; DNR MON  
T20N R2E S88°33'W 95.09'

DROVE 1 1/4" x 18" SOLID ROUND  
IRON.  
9" R PINE N10°E 51.35'  
11" R PINE S10°E 35.91'  
8" TW ASH S25°W 38.70'  
SET CEDAR POST WITH  
LOCATION TAG SOUTH 33'

Signed by Carl F. Roser

Date 9-27-95

Surveyor's Michigan License No. 12028