

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners in:

Ogemaw

(County)

Located In

Corner Code #

1. Public Land Survey

T 24N R 2E C-12  
T R

2. Property Controlling  
in Section

S 32 T 24N R 2E 12  
S T R

3. Miscellaneous  
Property in Section

S T R  
S T R

4. Lot No:

Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on October 24, 2005 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

12-This corner position was not established during the original government survey.

C-12 G.L.O. J.H. Mullet 1846 set quarter section post  
Wit: 6" Spruce Pine N75°W 08 links  
4" Spruce Pine N71°E 14 links

George Henning R.L.S. #2240 (1965) re-established the 1/4 corner at midpoint and on line

Wit: 8" J. Pine S55°W 48.5'  
10" J. Pine N46°W 67.5'  
12" J. Pine S44°E 72.6'

Liber 2, Page 202 1993 Timothy L. Lapham L.L.S. #27595 set a 1/2" capped iron to replace 3/8" bar removed during road construction.

Wit: S55°W 34.70' Power Pole  
N87°E 50.08' 6" X 8" Sign Post  
N81°E 59.11' 8" J. Pine  
S88°E 72.74' 10" J. Pine

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

12- Established the Northeast corner of the Southeast quarter of the Southwest quarter of section 32 as per B.L.M. instructions for the subdivision of a section.

C-12 Found a 1/2" iron rod fitting G. Henning's survey and T. Lapham's witnesses.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

12- Set 5/8" X 32" capped iron with P.S. cap #33981

Wit: 6" Cherry N54°W 18.09'  
6" Oak S56°W 76.92'  
17" J. Pine N80°E 102.03'  
8" Oak N15°E 107.81'  
Fence Corner post S & W N80°W 22.32'  
Carsonite Post East 5'±

C-12 1/2" iron rod

Wit: P. Pole S64°W 34.73'  
Sign Post N81°W 49.99'  
18" Oak S80°W 72.74'  
CTR N-S paved road West 0.5'

Signed by:

Carl T. Kiiskila

Date:

11/9/05

Surveyor's Michigan License No.:

33981

