

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

GOGEBIC - ONTONAGON Located In:
(County)

Corner Code #

1. Public Land Survey

T46N R 40W A - 12
T46N R 41W M - 12 *Gogebic*

2. Property Controlling
in Section

S T R SURVEY &
S T REMONUMENTATION

3. Miscellaneous
Property in Sec.

S T R
S T R MAR 02 2001

JUDITH D. ROEHM

1P

Ontonagon County

Page 1 of 1

LC 5/360

JEM Date 12/21/2000

Time 15:13:51

RECORDING FEE:

9.00

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____ SECTION _____

5. Private Claims _____

$\frac{1}{4}$ Corner common to Sections 31 & 36, T46N, R40 & 41W.
2000

I, Earl W. Applekamp, in a field survey on April 28, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by William Burt, U.S. Deputy Surveyor,
July 9, 1847.

ORIGINAL BEARING TREES:

7" Cedar N87°W 7 Links
10" Maple N49°E 28 Links

On January 19, 1976, Richard Drahn, R.L.S. 21564, recovered remains of the original bearing

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

trees and from this evidence set a 2"x5' long concrete filled galvanized iron pipe with a 3" circular bronze tablet stamped to read: T46N R40 -41W, $\frac{1}{4}$, S31, S36, RLS 21564, 1975. He established four bearing objects; 8" Red Maple, N47°E, 18.0 feet; 6" Yellow Birch, N44°W, 34.3 feet; 6" Yellow Birch, N78°W, 30.5 feet; 7' Metal Sign Post, West 2.3 feet. This corner was recorded in the Ontonagon County Register of Deeds Office in LC 1, page 40 on February 17, 1976.

I found the corner monument and bearing objects in good condition and re-painted the original bearing trees.

Research on file with the Ontonagon County Remonumentation Program Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I established one new bearing tree:

Nail in 5" Yellow Birch S66°E 21.20 Feet

DEAR GENTLEMAN AND LADY

Earl W. Applekamp

COUNTY CLERK 12-19-00

Signed by Earl W. Applekamp

Date December 9, 2000

Surveyor's Michigan License No. 17610

