

# SURVEY & REMONUMENTATION

MAR 02 2001

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

ONTONAGON  
(County)

Located in:

Corner Code #

1. Public Land Survey

T 48N R 40W

B - 1

T 49N R 40W

B - 13

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

JUDITH D. ROEHM

1P

Ontonagon County

Page 1 of 1

LC 5/348

JEM Date 12/07/2000

Time 14:40:57

RECORDING FEE:

9.00

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

$\frac{1}{4}$  Corner common to Sections 6 & 31, T48N T49N, R40W.

2000

I, Earl W. Applekamp, in a field survey on Nov. 09, 19X do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1	•											
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13	•											

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by John Burt, U.S. Deputy Surveyor, July 1847. Set Cedar Post.

ORIGINAL BEARING TREES:

18" Lynn N65°E 25 Links (16.50 Feet)  
18" Yellow Birch N45°W 15 Links ( 9.90 Feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. Area at corner has been farmed since the 1920's. Corner was re-established on a fence line running East and West for the latitude and by proportionate measure for the departure.

Research on file with the Ontonagon County Remonumentation Program Representative.

DEED GROUP APPROVED

Earl W. Applekamp  
COUNTY REGISTER

11-29-00

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a  $2\frac{1}{2}$ "X30" split base aluminum pipe with a 3" cap stamped to read: County Remonumentation, T48N, T49N R40W,  $\frac{1}{4}$ , S6, S31, 2000, P.S. 17610. I established three bearing trees and a reference object.

Nail in 6" Aspen S47°W 55.78' - Nail in 11" Aspen S51°E 48.92'  
Nail in 8" Aspen S11°E 72.00' - 6' Steel Sign Post, North 0.75'



Signed by Earl W. Applekamp

Date November 25, 2000

Surveyor's Michigan License No. 17610