

SURVEY & REMONUMENTATION

MAR 02 2001

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

ONTONAGON

(County)

Located In:

Corner Code #

1. Public Land Survey

T 48N R 40W

E - 4

T

R

T

R

T

R

T

R

2. Property Controlling in Section

S

T

R

S

T

R

3. Miscellaneous Property in Sec.

S

T

R

S

T

R

JUDITH D. ROEHM

1P

Ontonagon County

Page 1 of 1

LC 5/345

JEM Date 11/01/2000

Time 12:12:48

RECORDING FEE:

9.00

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

$\frac{1}{4}$ Corner common to Sections 8 & 9, T48N R40W.

I, Earl W. Applekamp, in a field survey on Oct. 18, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Wells Burt, U.S. Deputy Surveyor, June 2, 1851. Set Wood Post.

ORIGINAL BEARING TREES:

20" Sugar N34°E 21 Links (13.86 Feet)
10" Hemlock S18°E 33 Links (21.78 Feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. Construction of a County Road has destroyed all evidence. Corner was re-established by single proportionate measure between opposite corners North and South and in the center-line of the County Road. This position is in agreement with occupied lines East and West of the corner.

Research on file with the Ontonagon County Remonumentation Program Representative.

DEED GROUP APPROVED

Earl W. Applekamp 10-25-00
COUNTY REGISTER

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 5/8"x12" rebar with a 3" stamped cap 5" below top of gravel county road. I established a reference monument, a 2 1/2"x30" split base aluminum pipe with a 3" cap stamped to read: County Remonumentation, T48N R40W, 1/4, S8, S9, R.M., 2000. P.S. 17610. I also established three bearing trees.

REF. MON. S81°W 33.71' - Nail in 5" Oak N87°E 73.92'
Nail in 8" Ash N43°W 76.13' - Nail in 5" Maple S37°W 76.75'
6' Steel Sign Post S81°W 0.81 feet from Reference Monument



Signed by Earl W. Applekamp

Date October 23, 2000

Surveyor's Michigan License No. 17610