

JUDITH D. ROEHM

1P

Ontonagon County

Page 1 of 1

LC 5/325

JEM Date 07/28/2000

Time 15:18:50

9.00

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ONTONAGON

(County)

Located in:

Corner Code #

1. Public Land Survey

T48NR 41W

I - 2

2. Property Controlling
In Section

S T R

3. Miscellaneous
Property in Sec.

S T R

SURVEY & REMONUMENTATION

MAR 02 2001

SECTION

Register of Deeds Stamp & File Number

4. Lot No. _____ Recorded Plat _____

5. Private Claims _____

1/4 Corner common to Sections 2 & 3, T48N R41W.

I, Earl W. Applekamp, in a field survey on July 21, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2								
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original Corner established by Wells Burt, U.S. Deputy Surveyor,
June 17, 1851. Set Wood Post.

ORIGINAL BEARING TREES:

20" Sugar	N79°W	22 Links (14.52 Feet)
10" Hemlock	S56°E	14 Links (9.24 Feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. A 4"x4" yellow tag set by Champion, Inc. foresters identified as approximate Corner, was on a tree S59°E, 18' from the position I eventually set the monument.

Research on file with the Ontonagon County Remonumentation Program Representative.


DEED GROUP APPROVED

Earl W. Applekamp 7-26-00
COUNTY REGISTRAR

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2 1/2"x30" split base aluminum pipe with a 3" cap stamped to read: County Remonumentation, T48N R41W, 1/4, S2, S3, 2000, P.S. 17610. I established three bearing trees and a reference object.

Nail in 4" Red Maple	N59°W 51.39'	- Nail in 9" Aspen S70°E 63.17'
Nail in 9" Balsam	N01°W 53.37'	- 6' Steel Sign Post, South 0.65'



Signed by

Earl W. Applekamp

Date July 24, 2000

Surveyor's Michigan License No. _____

17610

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1999
REVISED JAN. 1999
REVISED OCT. 1995

325