

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ONTONAGON (County)	Located In:	Corner Code #
1. Public Land Survey	T48N R41W	J - 3
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
3. Miscellaneous Property in Sec.	S T R	

SURVEY &
REMONUMENTATION

MAR 02 2001

SECTION

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

$\frac{1}{4}$ Corner common to Sections 2 & 3, T48N R41W.

I, Earl W. Applekamp, in a field survey on May 17, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original Corner established by Wells Burt, U.S. Deputy Surveyor, June 20, 1851. Set Wood Post.

ORIGINAL BEARING TREES:

40" White Pine South 4 Links (2.64 feet)
10" Hemlock N30°W 18 Links (11.88 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. The Norwich Road, which has been in existence since the early 1900's, runs North & South along the $\frac{1}{4}$ line. At the calculated position of the corner I found a squared and painted wood post on the West side of the Norwich Road marked $\frac{1}{4}$. This had been installed by Champion Inc., timber cruisers. The latitude of the post was nearly on line with a recorded Section Corner $2\frac{1}{2}$ miles West. I used the squared wood post & the center-line of the Norwich Road as being the only logical position for the corner. I monumented the corner as described below.

Research on file with the Ontonagon County Remonumentation Program Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a $5/8$ "X12" rebar with a 3" cap, 2" below top of blacktop. Cap is stamped to read: County Remonumentation, T48N R41W, S2, S11, $\frac{1}{4}$, 2000, P.S. 17610. I established three bearing trees and a reference monument, a $2\frac{1}{2}$ "X30" aluminum pipe with a 3" stamped cap.

Ref. Mon. S68°E 40.14' - Nail in 26" W. Pine N65°W 71.25'
Nail in 4" Aspen S46°W 62.17' - Nail in 4" Aspen N61°E 49.52'

Signed by Earl W. Applekamp
Surveyor's Michigan License No. 17610

Date May 22, 2000

