

JUDITH D. ROEHM

1P

Ontonagon County

Page 1 of 1

LC 5/303

JEM Date 06/26/2000 Time 14:42:47

RECORDING FEE:

9.00

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ONTONAGON
(County)

Located In:

Corner Code #

1. Public Land Survey

T48N R41W

T49N R41W

T R

T R

S T R

S T R

S T R

S T R

H-1

H-13

2. Property Controlling in Section

3. Miscellaneous Property in Sec.

SURVEY & REMONUMENTATION

MAR 02 2001

SECTION

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

$\frac{1}{4}$ Corner common to Section 3, T48N R41W & Section 34, T49N R41W.

I, Earl W. Applekamp, in a field survey on June 12, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	10	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original Corner established by William A. Burt, U.S. Deputy Surveyor, summer of 1847. Set Cedar Post.

ORIGINAL BEARING TREES:

6" Cedar
12" Spruce

N29°E
N03°W

39 Links (25.74 Feet)
19 Links (12.54 Feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. Corner position lies in a cleared area, 50 feet +/- wide, which runs a mile West and $\frac{1}{2}$ mile East. Corner was re-established by single proportionate measure and on line with opposite Section Corners, East & West. This position is in Conformance with a creek call to the West.

Research on file with the Ontonagon County Remonumentation Program Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2 $\frac{1}{2}$ "X30" split base aluminum pipe with a 3" cap stamped to read: County Remonumentation, T48N, R41W, T49N, $\frac{1}{4}$, S34, S3, 2000, P.S. 17610. I established three bearing trees and a reference object.

Nail in 5" Aspen N35°W 55.63' - Nail in 7" Aspen S41°E 41.70'
Nail in 4" Aspen N44°E 86.87' - 6" Steel Sign Post South 0.55'



Signed by

Earl W. Applekamp

Date June 14, 2000

Surveyor's Michigan License No.

17610