CORNER RECORDATION CERTIFICATE Untonseon County

THIS COMMENTAL RECORDATION CENTIL ICATE	
Filing Requirement of Act 74, Mich. P. 435f9700f	1
- Filing Regultement of Act /4. Mich. P.A: 79/0" '	•
The state of the s	രുത്തു പടര് ഗ്ര

JEM Date 07/10/2000 RECORDING FEE:

LC 5/313 Time 12:13:36

9.00

For comers in

Located in:

Comer Code #

1. Public Land Survey

Ontonagon County

T52N R38W T51N R38W R Ŧ R R Ţ T R

2. Property Controlling in Section

S 3. Miscellaneous S Property in Sec.

SURVEY & REMONUMENTATION

MAR 02 2001

SECTION

Register of Deeds Stamp & File Number

4. Lot No.

, Recorded Plat

5. Private Claims

I, Joseph C. Domitrovich, in a field survey on June 2, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

6 7 10 25 11

A. Description of original monument and accessories and/or subsequent restoration:

(C-13) Corner of Sections 31 & 32, T52N, R38W & Sections 5 & 6 T51N, R38W

1845 - William A. Burt set a post with ties:

14" Sugar 12" Hemlock N 85°E N 30°W 50 links

38 links

I Found no Record of Subsequent Restoration.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found no remains of original comer or accessories. I re-established corner position at the intersection of centerline of Kujala Road to the North and on the extension of a very old but straight fence line to the East. Another old fence wanders westerly and southerly from this position. This position works very well with other section corners to the west. I placed a county monument at this position.

Research on file with County Remonumentation Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 5/8" x 24" iron pin with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; T52N, T51N, R38W; S. 31, S. 32, S. 5, S. 6; 2000; P.S. 37273. I also placed a reference monument, (R.M.) to the East, a 2 1/2" aluminum pipe with a 3" diameter aluminum cap stamped to indicate that the Section Corner is N 89°51'W 41.29'. Ties to the corner:

> R.M. \$ 89°51'30"E 41,29 Power Pole N 67°E 38.31" N 66°W 25.10° 6" Apple Tree 12" Elm S 14°W 49.71

NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted.

Surveyor's Michigan License No. 37273

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED JAN. 1975
REVISED JAN. 1975
REVISED JAN. 1975
REVISED JAN. 1975