RECORDING FEE:

1

2 3

6

7 8

9 10

11

12

JUDITH D. ROEHM Ontonason County

LAND CORNER RECORDATION CERTIFICATE of 1 Filing Requirement of Act 74, Mich. P.A. 970 6 06/12/2000

LC 5/290 Time 16:31:34 9.00

For comers in

Corner Code # **Ontonagon County** I neated in: T52N R39W I - 5 1. Public Land Survey R Т Ţ R R Т T R 2. Property Controlling R T S in Section S R Miscellaneous Property in Sec.

SURVEY & REMONUMENTATION

MAR 02 2001

SECTION

Register of Deeds Stamp & File Number G

22

4. Lot No.

. Recorded Plat

5. Private Claims

I, Joseph C. Domitrovich, in a field survey on May 22, 2000, do hereby state that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(L - 5) 1/4 Corner Common to Sections 12 & 13, T52N, R39W.

1845 - William A. Burt set a Sugar Post with ties:

16" Hemlock

N 17°E

37 links

14" Cedar

N 61°W

21 links

I found no record of subsequent restoration.

B. Description of comer evidence found and/or method applied in restoring or reestablishing comer:

I found no remains of the original corner or accessories. A paved North - South county road now runs along the N - S 1/2 line, and an old fence line runs along the North line of Section 13. I created a position for the 1/2 corner at the intersection of centerline of the county road and extension of fence lines East and West. This position works well with section corner to East and West as well as with long time occupation. I accepted the fence and centerline intersection as the 1/4 corner.

Research on file with County Remonumentation Representative.

C. Description of monument for comer and accessories established to perpetuate locating the position of the comer:

Comer is a 5/8" x 12" iron pin with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; T52N, R39W; ¼ S. 12, S. 13; 2000; P.S. 37273. I also established a Reference Monument (R.M.) to the east, a ¾" x 48" aluminum rod with a 3" diameter cap stamped to indicate that the 1/2 corner is S 89°54'W, 28.16'. Ties to the corner:

S 59°E 33.01 Power Pole N 84°W 35.57 8" Red Pine 41.01' 12" White Pine N 49°E R.M. N 89°54'10"E 28.16 N 89°44'18"E 2628 041 NE Cor. Sec. 13 2654.19 S 89°28'44"W NW Cor. Sec. 13

NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted.

5/24/00

OF MICH IOSEPH DOMITROVICH LAND SURVEYOR No. 37278 CAND