Ontonagon County

LAND CORNER RECORDATION CERTIFICATE of 1 Filing Requirement of Act 74, Mich. P.AjE 970te 06/12/2000

LC 5/292

RECORDING FEE:

Time 16:32:11 9.00

For corners in

Miscellaneous

5. Private Claims

Comer Code # Located in: **Ontonagon County** T52N R39W ( M-6 1. Public Land Survey T52N R38W T R Ŧ R R S T 2. Property Controlling S T R in Section R

S

SURVEY & REMONUMENTATION

MAR 02 2001

SECTION

Register of Deeds Stamp & File Number


Property in Sec. S , Recorded Plat Lot No.

I, Joseph C. Domitrovich, in a field survey on May 22, 2000, do hereby state that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

T

R

Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

(M - 6) ½ Corner Common to Sections 13, T52N, R39W & Section 18, T52N, R38W.

1845 - William A. Burt set a Fir post with ties:

12" Sugar

N 58°F

24 links

26" Hemlock

S 35°W

7 links

I found no record of subsequent restoration.

B. Description of comer evidence found and/or method applied in restoring or reestablishing comer:

I found no remains of original corner or accessories. At the corner position is East - West gravel Aho Road and a fence line running North. I established a position for the 1/4 comer in centerline of the road on the extension of the fence to the North. This position works well with section comer to North and with other comers on the Range line to the South. It also works well with 1/16 fence to the West. I accepted this position as the ¼ corner.

Research on file with County Remonumentation Representative.

C. Description of monument for comer and accessories established to perpetuate locating the position of the comer:

Comer is a 5/8" x 24" iron pin with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; T52N, R39W; R38W; 1/4; S. 13, S. 18; 2000; P.S. 37273. I also established a reference monument (R.M.) to the North, a 2 1/2" x 30" aluminum pipe with a 3" diameter cap stamped to indicate that the 1/4 corner is \$ 00°27'W, 31.372 **Ties** to of Mica the corner:

6" Soft Maple S 60°E 44.31' S 44°W 38.08' 14" Ash Power Pole N 73°W 98.70 N 00°27'00"E 31.37 R.M. 2648.93' N 00°23'27"E NE Cor. Sec. 13

JOSEPH DOMITROVICH LAND SURVEYOR 37273

NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted.

epplekang 5-24-00 B22 COLUMN

5/24/00

Surveyor's Michigan License No. 37273

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1985 REVISED DOT., 1985