

NO. 15 of 16

Osceola COUNTY

T 19 N, R 8 W

ITEM 2 SEC. 29 CODE 16

DESCRIPTION E 1/16 on S. line Sec 29

DATE SET 6-16-80 RH:KV

(✓ LTR 7-16-80)

(C) COR. MON. set $\frac{5}{8}$ " x 34" re-rod w/RLS cap

W $\frac{1}{4}$ Ced Post w/10c tag

I

T

N 14" Sugar Maple N 30° W 25.9'

E

S 11" Ash S 65° E 13.8'

S

E 10" Maple in clump 3 S 35° W 16.1'

S Crooked Smooth wire N-S on trees Due W 42'±

RESTORATION PROCEDURES (A and/or B)

(B) Estab. E 1/8 Cor. on S. line

S-29, mid-way $\frac{1}{4}$ on line

between SE Cor. & S 1/4 Cor. of

S-29,