

SURVEY & REMONUMENTATION

DEC 16 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Osceola

(County)

Located In:

Corner Code #

- | | | |
|------------------------------------|-------------|-----|
| 1. Public Land Survey | T 20N R 10W | G-8 |
| | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling in Section | S T R | |
| | S T R | |
| 3. Miscellaneous | S T R | |
| Property in Sec. | S T R | |

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Matthew McClung in a field survey on 10-7, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

The original corner was set by deputy surveyor Sylvester Sibley on 7 July 1838. Set wood post 40.00 chains from South.

Pine 20" N72W 5 Lk.

Hemlock 10" S68E 35 Lk.

I have shown 1 L.C.R.C.: Liber 2, Page 113.

I have shown 1 PA 352: Liber 417.

Burdell Township Book; Pages 88 and 89 and pages 32, 33, 34 and 35.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1 1/4" X 18" long iron pipe 1 foot East of centerline of North and South Road, in fence row to East 4" below road surface. Excavated to 14" and found 5/8" iron rod. Placed top of Osceola County Monument over cent of 5/8" iron rod 6" below road surface.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner G-8. Osceola County Monument, which is a 3" brass cap mounted on a 1" pipe 18" in length.

Power Pole N52W 39.88 RLS Tag. O.B.P.

20" Maple S78W 26.28 O.B.T.

16" Maple w/nail N22E 61.85 feet.

8" Maple N25W 72.85 feet.

Signed by

Matthew McClung

Surveyor's Michigan License No.

13037

Date 7, 1996



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1985