* SURVEY & REMONUMENTATION

DEC-0 6 1993

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970				
Fo	r corners in			
	Osceola (County)	Located In:	Corner Code ##	
1.	Public Land Survey	T R T R T R	K-13	APPROVED LAND CORNER P.A. 345 OF 1990 Osceola County
	Property Controlling in Section Miscellaneous Property in Sec.	T R S T R S T R S T R		Register of Deeds Stamp & File Number
4. 5.	Lot No , Private Claims	Recorded Plat		A B C D E F G H I J K L
			,	2 6 5 4 3 4 2
				3 4 7 9 9 9 9 9 9 9
Ι, _	Matthew McCli	ung Oct	tober 17, 93	5 1 1 1 1 1 1
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded				
NC	on this certificate		a range, may be recorded	11 12 31 32 33 34 35 36
В.	Beech 11' Pine 7" N From 1891 to program, in w most part, a at each gover tile per corr Description of corner of Found Tile, a so the top of	od post 80.00 chains of N62E 12 lks. N18W 36 lks. 1904 approximately, which surveyors Temp 3" glazed tile fill rnment set corner in her, placed atop of evidence found and/or method appared sucker rod, Males of the rod is 10" easier of the tile, 8" be	s from the South , Osceola County ple and Trumbull led with cinders n the township. each other, (couplied in restoring or reested end. The suckets st of the tile.	John Hodgson on Sept. 24, neast Corner of Section 36. y had a remonumentation 1, did the work. For the 5 from a forge, were placed There were supposed to be 3 continued on back) ablishing corner. er rod is bent to the east, Set Osceola County Monument
	Corner K-13. 1" pipe 18" i 6" steel 6" steel Power po 6" W. pi	Osceola County Monuin length. I pipe gate post, in length pipe gate post, in ole and telephone rine S35W 58.15 feet.	ument, which is a concrete S80E a concrete S55E iser N30W 51.55	39.83 feet. feet. OF MICHE A. McCLUNG LAND SHEVEYOR
3igr	ned by Muthuw	Milley	Date	November 78 1993 No. 13037

OSCEOLA COUNTY REGISTER OF DEEDS

93 DEC -1 AM 9: 43

nancy Crassford

thereby making the corner 4 feet long. Sometimes a solid tile, with a cross in the top was used, and sometimes a 1/2" iron bars were added to the tile. Notes of the work were kept in ledgers, and given to the townships, and 5 of the townships have been recorded in the County records.

This corner was found and used in a 1913 survey for section 35, pages 42 and 43 of the Highland Twp. book. the corner was called tile, Witnesses: Pine Stp. S65 1/2W 48.9 - Pine stp. S50 1/2E 64.7 - top of stone NW 6.0 .

I used this corner in 1973, in a survey for Highland Heights subdivision, and recorded a PA. 74 certificate.

The corner was used again in 1990, for a survey recorded in Liber 516, pages 449 & 450.