

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oscoda

(County)

Located In:

Corner Code #

1. Public Land Survey

T 26N R 2E

A - 5

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Section

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Liber 4 pg. 60

STATE OF MICHIGAN  
OSCODA COUNTY  
FILED

2 AUG 95 9:35 A.M.

PATSY J. PETERS

REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Marvin E. Myers, in a field survey on May 19, 19 95,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current  
manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and  
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a  
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found  
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO-Clason May 1839

Mon-Post

WIT: 10" Spruce S29°W 31 lks.  
10" Spruce N67°W 28 lks.  
8" Spruce S72°E 12 lks.  
14" Spruce N22°E 23 lks.

C.O. Seeley May 23, 1912

Mon-Set Post

WIT: 7" B.Oak N31°W 50 lks.

C.O. Seeley May 30, 1914

Mon-Remarked Corner  
from old survey

Mon: unknown

WIT:

C.O. Seeley Sept. 21, 1914

Mon-Unknown (set by previous survey)

WIT: None given

GLO-G. Veal Oct. 1935

Mon-Set Conc. Mon. with

Brass Tablet by proportionate distance

WIT: 8" J.Pine N61°E 48 lks.  
8" J.Pine S04½°E 60 lks.  
6" J.Pine S39½°W 26½ lks.  
12" B.Oak N28½°W 48 lks.

G.D. Henning 1953

Mon-Fd. US GLO Mon. broken

Set RR spike over it

WIT: NBT Spike in 10" J.Pine N48½°E 47.00'  
NBT Spike in 7" J.Pine S21°W 51.20'

G.D. Henning Aug. 1956

Mon-US GLO Mon. broken off

WIT: Spike in 10" J.Pine N48½°E 47.00'  
Spike in 7" J.Pine S21°W 51.20'

G.A. Shadko 1958

Mon-US GLO Mon.

WIT: None given

L.4, pg.489 N. Caldwell July 16, 1990

LCRC L.3, pg. 90

Mon-Fd. 5/8" Bar in Mon. Box

WIT: 10" J.Pine S30°E 79.91'  
Red Top Post N32°W 38.60'  
7" J.Pine N38°E 59.55'  
6" J.Pine S51°E 56.75'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 5/8" Bar & Cap in Monument Box. Replaced cap with standard Oscoda County Cap.  
Accepted as the best available evidence of the position of the Original corner.

APPROVED

County Remonumentation  
Peer Review Group

NCC/31/2006 95  
JULY

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon-5/8" Bar & Cap in Mon. Box

WIT: 10" J.Pine S35°E 79.91'

Nail in SW face Red Top Post N25°W 38.60'

Centerline N-S road East 10.50'

Fd. nail SW face 7" J.Pine N45°E 59.55'

Fd. nail NE face J.Pine S45°E 56.75'



Signed by

*Marvin E. Myers*

Date

*July 28, 1995*

Surveyor's Michigan License No.

31600