

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Oscoda

(County)

Located In:

Corner Code #

1. Public Land Survey

T 26N R 2E
T 25N R 2E
T 26N R 1E
T 25N R 1E

A-13 ✓
A-1
M-13
M-1

2. Property Controlling
in Section

S T R
S T R

3. Miscellaneous

S T R

Property in Section

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, Marvin E. Myers, in a field survey on June 13, 1995,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO-L. Clawson May 1839
Mon-Post
WIT: 12" Tamrack S38°E 26 lks.
12" Cedar N44°W 18 lks.

GLO-Guy Veal 1924
Mon- Replaced wood post
WIT: with 3"x36" Iron post
with brass cap.

GLO-Guy Veal Oct. 1935
Mon-Fd. 36"x3" Iron Post
WIT: 6" Cedar N19½°E 39.9

C.O. Seeley Sept. 1914
Mon-Post in Swamp
WIT: Fd. USBT
East Brook at 2,54 chs.

Wit- Fd original bearing
trees & added new
12" Cedar N77°30'E 471ks
6" Cedar S32°15'E 1041ks
8" Cedar S53°30'W 401ks
14" Cedar N41°30'W 271ks

L.I, pgs. 121 & 122 L. Cavanagh Oct. 31, 1973
Mon-Pipe
WIT: 6" Cedar N19½°E 39.90'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found US GLO 3" pipe monument in North edge of creek flowing East. Accepted as a perpetuation of the original Governme
corner.

APPROVED

County Remonumentation
Peer Review Group

NCC/31/706 95
JULY

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon-3" pipe with Brass Caps US GLO Mon.
WIT: Bank Creek North 1.0'
Nail NE side 14" Cedar N38°W 17.91'
Nail West side 3" Balsam N01°W 4.77'
Nail West side 12" Cedar N26°E 39.60'
Nail North side 16" Cedar S64°E 18.95'
Nail East side 9" Cedar S40°W 12.00'



Signed by

Marvin E. Myers

Date

July 20, 1995

Surveyor's Michigan License No. 31600

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983