

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

OSCODA

(County)

Located In

Corner Code #

1. Public Land Survey T 27N R 1E J-13  
T R
2. Property Controlling in Section S 35 T 27N R 1E 6  
S T R
3. Miscellaneous Property in Section S T R  
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on January 16, 2001 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

J-13 G.L.O. Lewis Clawson May 1839

Set quarter section post

Wit: Spruce 8 N62°W 21 Links  
Spruce 9 N50°W 1.20 Chains

6- G.L.O. This corner position was not established during the original government survey

In the spring of 1937 Guy R. Veal did a dependent resurvey of the south line of section 35 T.27N.,R.1E for the Department of the Interior General Land Office. He re-established the corner by proportionate distance. He set a concrete monument with a brass cap. Wit: 5" Jack Pine N73°E 41 links  
6" Jack Pine S30.5°W 71 links  
A local corner 4"X 4" X 30" wood post N59°W 27 links



B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

J-13 Found concrete monument with brass cap

6- Established the Northeast corner of the Southwest quarter of the Northeast quarter of section 35 per B.L.M. instructions for the subdivision of a section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-13 Found concrete monument with 3.5" brass cap

Wit: \*16" Oak S07°E 32.84'  
4" White Pine N77°W 19.39'  
14" Red Pine N31°E 23.69'  
4" Balsam S71°E 30.93'  
1½" iron pipe with brass cap S84°E 5.60'  
Carsonite post North 1'±

6- Set 5/8" X 32" rerod with P.S. cap #33981

Wit: 20" White Pine N62°E 25.40'  
3"-5" Triple Maple N28°W 17.88'  
10" White Pine West 5.08'  
6" White Pine S05°W 26.72'  
Carsonite Post North 1'±

\* Old witnesses by others

Signed by:

Carl T. Kiiskila

Date:

6-14-01

Surveyor's Michigan License No.:

33981