

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

Liber 5 pg 56

For corners in

OSCODA

(County)

Located In: ELMER

Corner Code #

STATE OF MICHIGAN  
OSCODA COUNTY  
FILED

15 SEP 1999 9:37:03 AM

PATSY J. PETERS  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. Public Land Survey

T<sub>27N</sub> R<sub>2E</sub> B-9

T R

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, FREDERICK J. KING, in a field survey on JUNE 7, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

B-9 - 1/4 CORNER COMMON TO SECTIONS 19 & 30

Nov. 1839 - William R. Coon - Dep Sur. - Set Original Post - N10°W-13 lks (8.58') 12" Pine \* S22°E-12 lks (7.92') 10" Aspe  
Oct. 1943 - Survey by G.D. Henning, PS#2240 - Fnd 1/4" Pipe In Line Fence to South and Orig. US BT Stump was found  
to North \* N52°E-143.6' -12" J. Pine \* N41°W-33.7' - 10" Birch

Nov. 1972 - Act 132 by N.C. Caldwell, PS#12018 - Fnd Rec. 1 1/4" Pipe - Same Wit as Henning -(Rec. L. 1, Pg. 250)

Jan. 1981 - Act 132 by F.J. King, PS#25852 - Fnd I&C #12018 - No Wit (Not Recorded)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-9 - 1/4 CORNER COMMON TO SECTIONS 19 & 30

Fnd 1/2" Iron (No Cap) Inside of 1 1/4" Pipe In C.L. Rd.

APPROVED

County Remonumentation  
Peer Review Group

7 SEPT 99  
NCC

THIS CORNER WAS APPROVED BY OSCODA COUNTY PEER REVIEW ON JULY 9, 1999, AS A PERTETUATION OF THE ORIGINAL GOVERNMENT CORNER

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-9 - 1/4 CORNER COMMON TO SECTIONS 19 & 30

Placed Oscoda County Re-Mon Cap on Fnd 1/2" Iron  
N65°E - 48.80' - Set S&T on NW side 10" Oak  
SOUTH - 32.8' - N face of USFS Post  
S05°W - 24.62' - Set S&T on W side of 15" R. Pine  
S65°W - 53.48' - Set S&T on SE side of 15" R. Pine  
N60°W - 42.32' - Set S&T on SW side of 20" R. Pine  
Corner Is - 1' N of C.L. E-W Gravel Rd. (Kneeland Rd.)



Signed by Frederick J. King

Date August 28, 1999

Surveyor's Michigan License No. 25852