

DEC 21 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oscoda

(County)

Located In:

Corner Code #

1. Public Land Survey

T 27N R 2E

E-4

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, Marvin E. Myers, in a field survey on June 29, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration.

¼ corner common to Sections 8 and 9, T27N, R2E

GLO 1839 W. Coon, DS

1887 John Randall C.S.

Mon. - Post

Mon. - Post

Wit: 4" Dwarf Oak N12°E 16 lks

Wit: 30" Y. Pine S76°E 1.38

4" Dwarf Oak S29°W 11 lks

No Other

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

¼ corner common to Sections 8 and 9, T27N, R2E

No evidence found of corner or subsequent restoration was found, reestablished corner by single proportion measure between E-5 and E-3. Set 5/8"x34" steel rebar with Standard Oscoda County Remonumentation Cap. This position was accepted as a careful and faithful reestablishment of the position of the Government Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

¼ corner common to Sections 8 and 9, T27N, R2E

Mon - Standard Oscoda County Monument

Wit: Nail & tag in 10" J. Pine S58°E 27.20

Nail & tag in 10" Maple (4 in clump) S23°E 20.00

Nail & tag in 2" Poplar N68°W 5.00

Nail & tag in 4" J. Pine S25°W 15.75

APPROVED

County Remonumentation
Peer Review Group

NCC

27 JULY 00



Signed by

Marvin E. Myers

Date July 11, 2000

Surveyor's Michigan License No. 31600

SECTION

