

**LAND CORNER RECORDATION CERTIFICATE**

**Filing Requirement of Act 74, Mich. P.A. 1970**

**SECTION**

STATE OF MICHIGAN  
OSCODA COUNTY  
FILED

For corners in

<u>Oscoda</u>	Located In:	Corner Code
# (County)		
1. Public Land Survey	Sec. <u>T 27N R 2E</u>	<u>H-9</u>
	Sec. <u>T R</u>	
	<u>T R</u>	
	<u>T R</u>	
2. Property Controlling	S <u>T R</u>	
In Section	S <u>T R</u>	
3. Miscellaneous	S <u>T R</u>	
Property in Sec.	S <u>T R</u>	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

3 SEP 1999 1:49:04 PM

PATSY J. PETERS  
REGISTER OF DEEDS

*Liber 5 pg 29*  
Register of Deeds Stamp & File  
Number

I, Marvin E. Myers, in a field survey on June 22, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

H-9 = 1/4 corner common to Sections 22 & 27, T27N, R2E

G.L.O. Nov 4<sup>th</sup> 1839 W. R. Coon D.S.

Mon: Post

Wit: 6" Birch N34 1/2°W 52 lks

8" Birch S41°W 17 lks

June 17<sup>th</sup> 1968 N. Caldwell, #12018

Mon - Fd. Consumers Power "T" Iron

Wit: 8" Maple S58°E 58.8'

4" Maple N15°W 35.1'

4" Maple N55°E 55.8'

Aug 28<sup>th</sup> 1911 C. Seeley Co. Surveyor  
Book 2, Page 17

Mon - Set New Post by US BT

Wit: NBT 4" Fir S61 1/2°W 62 1/2'

L2, P601 June 1<sup>st</sup> 1978 N. Caldwell #12018

Mon - Fd. Record Iron replaced on this date

with Standard County corner

Wit: 6" Maple N10°W 34.6

6" Maple N60°E 55.6

Fence Cor. Post South 35.5

LCRC L1, P.207 June 1<sup>st</sup> 1978

same as above

Sept 25<sup>th</sup> 1990 F. J. King, #25852

Mon - Fd. Rec. Co. Cor.

Wit: rec. Bk. 1, P. 207

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-9 = 1/4 corner common to Sections 22 & 27, T27N, R2E

Found Standard Oscoda County Monument; found 1/2" bar & cap #18654 South 33.00; found 6" Maple N60°E 55.6; found fence post South 35.5.

Accepted Standard Oscoda County Monument as the best available evidence of the Position of the Original Government Corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-9 = 1/4 corner common to Sections 22 & 27, T27N, R2E

Mon - Standard Oscoda County Monument

Wit: 1/2" bar & Cap #18654 South 33.00

Nail & tag W. side 6" Maple N10°W 36.25

Nail & tag NW side 8" Maple N60°E 55.85

Nail NE side 5" Maple N45°W 43.09

**APPROVED**

County Remonumentation  
Peer Review Group

*19 AUG 99*  
*NCC*



Signed by Marvin E. Myers  
Surveyor's Michigan License No. 31600

Date August 14, 1999