APR 2 5 1995

For corners in

expressed below:

## COMMISSION

## OTSEGO COUNTY REMONUMENTATION

## LIBEROOOL PAGEOII LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

ALSO Act 345, PA 1990

_	OTSEGO (County)	Located In:	Corner Code ##
1.	Public Land Survey	T 30 N R 4 W	F-3
		T R	
		T R	
		T R	
2.	Property Controlling	S T R	
	in Section	S T R	
3.	Miscellaneous	S T R	
	Property in Sec.	S T R	

OTSEGO COUNTY MICHIGAN RECEIVED FOR RECORD

94 DEC 14 PM 4:01

EVELYW M. PRATT CLERK / REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No, Recorded Plat			_			_				
5. Private Claims	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		В	<u> </u>	D E	<del>_</del> F	G	H 1		_
		2	· 6	<u> </u>	<u>.</u>	_   _		<u> </u>	}	_
		٦L	_İ	LĬ		Ĺ		ĭ. l	Ī	
·			Ţ			-Y-	T		$\neg$	Т
Carl I. Robinson , in a field survey on December 12,19	94		7-	Γi	<u>'</u>	-9- 	<b>-</b>	P	—; ; 	<b>;</b> —
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points in	mantioned	-}-	+	1		- -		╁─┼		_
n lines 1 and 2 above were in conformance with regulations and rules therefore as required in the				17	7	-16-	<del> </del> -1	5	14	<b></b>
current manual of survey instructions of the United States Department of the Interior, Bureau of Land				<b> </b>	_			ļļ.		
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5					L	_] _21_			1	
bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Do		9	1	[ ]	Τ		T	í	-23 	-
Court of Law: established re-established monumented re-monumented recovered to	found as	" ├─	-	<del></del>			+-		-	

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1/499: A.P. Brewer, 1856: Post-Sugar N 68°E 14 lks (9.2'), Sugar 10 S 26°W 35 lks (23.1').

CSR 1/32: J.W. Sanborn, 1884: Sugar 5 26°W 35 lks (23.1'-Ed. GLO B), Sugar 18 N 49°E 39 lks (25.7').

CSR 3/18: G.F. DeLamater, 1934: Found old Post, ½"x30" bar in corner-Concrete Monument North 33.0', Elm 24 N 63°W 63.8'.

LCR 1/455: P.E. Chenard, 1975: Found Boat Spike & 2 witnesses recorded in County Survey Records-Concrete Monument North 33.00', 24" Elm N 63°W 63.97', P.Pole S 70°W 94.65', R.Pine N 15°E 62.30'.

CS 281/29-31: C.I. Robinson, 1980: Found RR Spike over ½" Iron Rod, set Otsego County Monument-tag #14200 24" Elm N 63°W 63.97', 4" Iron Pipe Monument North 33.00', tag #14200 P.Pole S 70°W 94.65', tag #14200 R. Pine N 15°E 62.27'.

Misc.: C.I. Robinson, 1991: 32" Maple N 83°E 136.37', F. Post North 33.87'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner;

Found Otsego County Monument in centerline of pavement east & west, concrete monument, R. Pine & P. Pole witnesses, also 24" Elm stump and 1991 witnesses. The witnesses and records trace back to the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Otsego County Monument in centerline of pavement east & west and on fence line north & south is accepted as a careful and faithful perpetuation of the position of the original corner.

4" Pipe Monument North 33.00', tag #14200 14" R. Pine N 15°E 62.20', spk 28" Maple N 83°E 136.37', tag #14200 P. Pole S 70°W 94.74', 24" Elm stump (very rotten) N 63°W 63.97'

> E OF MICHIC CARL I. ROBINSON ROFESSIONAL SURVEYOR No. 16390

## OTSEGO COUNTY REMONUMENTATION

Approved by the County Survey Peer Group, pursuant to Act 345, PA 1990. V. Chairman Date

WAS ESSION December 13, 1994 I. Robinson.

Otsego County Surveyor PE & PS, Surveyor's Michigan License No. \_ 16390

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983