

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. PA 1970

For Corners In:  
OTSEGO  
(County)

Located In

Corner Code #

1. Public Land Survey  
T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_  
2. Property Controlling  
in Section  
S 12 T 31N R 1W 13  
S 12 T 31N R 1W 16  
3. Miscellaneous  
Property in Section  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Carl T. Kiiskila, in a field survey on July 22, 2013 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

13 SE 1/16 Corner, Section 12, T31N,R01W

16 E 1/16 Corner, South line Section 12, T31N,R01W

This corner position was not established during the original Government survey.

This corner position was not established during the original Government survey.



OTSEGO COUNTY MICHIGAN  
RECEIVED FOR RECORD  
SUSAN DEFUYER, CLERK/REGISTER OF DEEDS  
11/06/2013 1:57:12 PM

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

13 SE 1/16 Corner, Section 12, T31N,R01W

16 E 1/16 Corner, South line Section 12, T31N,R01W

Established the Southeast 1/16 corner of section 12 per B.L.M. instructions for the subdivision of a section.

Established the East 1/16 corner on the South line of section 12 per B.L.M. instructions for the subdivision of a section.

Set a stamped 2" dia. aluminum cap on 5/8" rebar.

Set a stamped 2" dia. aluminum cap on 5/8" rebar.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

13 SE 1/16 Corner, Section 12, T31N,R01W

16 E 1/16 Corner, South line Section 12, T31N,R01W

Stamped 2" dia. aluminum cap on 5/8" rebar.

Set a stamped 2" dia. aluminum cap on 5/8"x34" rebar.

Wit: N64°E 19.25' to set N&T on NW side 12" R. Pine  
S53°E 7.72' to set N&T on NE side 3" R. Pine  
S9°W 5.34 to set N&T on E side 9" R. Pine  
N61°W 5.40' to set N&T on SW side 11" J. Pine  
Set Blue Post w/location tag 1' North

Wit: N59°E 33.66' to set N&T on NW side 12" J. Pine  
S42°W 67.66' to set N&T on SE side 13" R. Pine  
S78°W 53.29' to set N&T on S side 10" R. Pine  
N48°W 52.87' to set N&T on NE side 12" R. Pine  
Set Blue Post w/location tag 1' North

Carl T. Kiiskila

Surveyor's Michigan License No.: 33981



11-6-13