

OTSEGO COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Located In Charlton Corner Code #  
Otsego Twp. North  
(County)

1. Public Land Survey	T	31N	R	1W	K-5
	T		R		
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on September 3, 2013 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

K-5 Corner common to Sections 11&12, 13&14 T31N, R01W

1850 – GLO – Austin Burt- Set post of corner  
11,12, 13 & 14  
Spruce 12 S35W 44  
Fir 8 N73W 35

No Date Marcus Schaaf RLS #3104 index  
shows he " found or established and replaced".

1978- Unrecorded LCRC Louis J. Czubak P.S. #12581  
Fd Cedar Post  
11" Cedar N10°W 26.78'  
9" Cedar N62°W 34'  
Found Cedar stump S42°W 31.20'  
Replaced w/ 5/8" x 24" Bar

1981- Liber 2,page 208 Danny M. Bongiovanni  
P.S. #24586 Fd Cedar Post  
11" Cedar N10°W 26.78'  
9" Cedar N62°W 34'  
Cedar stump S42°W 31.2'  
Replaced w/ 5/8" x 24" Bar

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

K-5 Corner common to Sections 11,12, 13&14 T31N, R01W

Found a 5/8" bar with P.S.Cap #12581 and  
a 2" x 3' pipe laying 12" below grade  
N64°W 33.75' to 11" Cedar snag  
Drove 1" x 5' pipe over found 5/8" bar.

DNR Monument accepted as the best  
available evidence of the corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-5 Corner common to Sections 11,12, 13&14 T31N, R01W  
Stamped 4" diameter DNR aluminum cap on 1" x 5'  
galvanized pipe.

Wit: N28°E 30.03' to set N&T on W side 4" Tamarack  
S22°E 32.92' to set N&T on E side 4" Tamarack  
N64°W 33.75' to set N&T on N side 11" Cedar snag  
S80°W 14.30' to set N&T on N side 3" Tamarack  
Reset 2" pipe N62°W 0.60'  
Small stream East 17'  
Set Blue Post 1' North

Signed by: Carl T Kiiskila  
Surveyor's Michigan License No.: 33981

Date: 10-14-13

