

OTSEGO COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE

LIBER 0004 PAGE 83

Filing Requirement of Act 74, Mich. P.A. 1970
ALSO Act 345, PA 1990

For corners in

OTSEGO (County)	Located In:	Corner Code =#
1. Public Land Survey	T 31 N R 2 W	M-9
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

OTSEGO COUNTY
MICHIGAN
RECEIVED FOR RECORD

95 NOV -2 AM 10:14

EVELYN M. PRATT
CLERK / REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Carl I. Robinson, in a field survey on July 10, 1995,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L
2	5	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	13	17	15	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

- A. Description of original monument and accessories and/or subsequent restoration:
GLO 2/9: John Mullet, 1840: Set Post-Sugar 24" N 6°E 10 lks (6.6'), Beech 18" S 25°W 43 lks (28.4').
CSR 2/260: G.F. DeLaMater, 1922: Found Gov't B & P, long Iron Rod at corner-Cor. Fence S 41°E 57 lks (37.6'),
Hemlock stump 14" S 8°E 30 lks (19.8'), Corner House N 45°W 128 lks (84.5'); 1936: Pointed Stone N 41°E
37.7', Concrete Monument N 45°E 48.0'.
CSR 3/282: S.O. Thorsen, 1953: Place 1/2"x48" bar over 1" bar at surface of road-Elm 10" N 84°W 42.0', Concrete
Monument (broken up) S 45°W 48.0', Corner House N 45°W 84.5' O.K.
LCR 1/457: P.E. Chenard, 1975: Found Thorsen's 1/2" Bar, Concrete Monument & Elm-P.Pole N 45°E 39.20', Concrete
Monument S 45°W 48.05', 24" Elm (dead) N 84°W 42.13', G.Pole N 60°W 43.18'.
Misc.: C.I. Robinson, 1980: Set Otsego County Monument
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
Found Otsego County Monument (4" extendable), DeLaMater's Concrete Monument, and Chenard's P.Pole & G.Pole.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Otsego County Monument in corner is accepted as a careful and faithful perpetuation of the position of the original
corner-spike P.Pole N 60°E 39.20', spike 22" Ash S 48°E 90.38', Concrete Monument (broken) S 52°W 48.06', tag G.Pole
N 50°W 43.10'.



OTSEGO COUNTY REMONUMENTATION

Approved by the County Survey Peer
Group, pursuant to Act 345, PA 1990.

8/3/95
Date

D. C. E. Sagan
Vice Chairman

Signed by Carl I. Robinson
Carl I. Robinson, PE & PS, Otsego County Surveyor
Surveyor's Michigan License No. 16390

Date July 18, 1995