

LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>ONTONAGON</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T48N R39W	K-11
	T___ R___	_____
	T___ R___	_____
	T___ R___	_____
2. Property Controlling in Section	S___ T___ R___	_____
	S___ T___ R___	_____
3. Miscellaneous Property in Sec.	S___ T___ R___	_____
	S___ T___ R___	_____

REPRESENTATIVE
 OCT 9 0 1997
 COMMISSION

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

Section Corner common to Sections 25, 26, 35 & 36, T48N R39W.

I, Earl W. Applekamp, in a field survey on June 21, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Artemas Curtis, U.S. Deputy Surveyor, September 1851. Set Wood Post.

ORIGINAL BEARING TREES:

12" Sugar Maple N60°E 19.80 feet
 20" Hemlock S36°W 8.58 feet

PEER GROUP APPROVED
Earl W. Applekamp
 COUNTY REPRESENTATIVE
 7-15-97

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. An old gravel road runs East & West from the ~~corner~~ apparent corner position. A very old fence (60 years ±) runs North from the site. All timber was recently cut West of this line. A 70 year old resident, Reino Nurkkala who owns the NW $\frac{1}{4}$ -NW $\frac{1}{4}$ of Section 36, said the fence was the line. Distances to a creek West and corners North, East & West are in conformance with G.L.O. I re-established the corner on line with the fence line and in the centerline of the gravel road.

Research on file with the Ontonagon County Remonumentation Program Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 5/8"x12" rebar in the centerline and 6" below the gravel road. I established a reference monument, a 2 1/2"x30" aluminum pipe with a 3" cap stamped to read: County Remonumentation, T48N R39W, R.M., S25, S26, S35, S36, 1997, P.S. 17610. I also established three other bearing objects.

REF. MON. N26°E 35.98' - Power Pole S69°W 123.51'
 Power Pole S75°E 150.10' - 7" Hard Maple N46°W 48.21'



Signed by Earl W. Applekamp
 Surveyor's Michigan License No. 17610

Date June 25, 1997