

JUDITH D. ROEHM

1F

Ontonagon County

Page 1 of 1

LC 5/234

JEM Date 10/27/1999

Time 14:24:33

FILING FEE:

9.00

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ONTONAGON

(County)

Located in:

Corner Code #

1. Public Land Survey

T48N R 41W

C-12

T___ R___

T___ R___

T___ R___

T___ R___

2. Property Controlling
In Section

S___

T___ R___

S___

T___ R___

3. Miscellaneous
Property in Sec.

S___

T___ R___

S___

T___ R___

**SURVEY &
REMONUMENTATION**

MAR 28 2000

SECTION

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

1/4 Corner common to Sections 31 & 32, T48N R41W.

I, Earl W. Applekamp, in a field survey on Oct. 01, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Wells Burt, U.S. Deputy Surveyor, June 12, 1851. Set Wood Post.

ORIGINAL BEARING TREES:

| | | | |
|-------|-----|-------|----------------------|
| Elm | 16" | S28°E | 7 Links (4.62 feet) |
| Cedar | 12" | N03°W | 12 Links (7.92 feet) |

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. Area has been logged 3 times and burned over around 1920. Corner was re-established by single proportionate measure and on line between opposite Section corners North & South.

Research on file with the Ontonagon County Remonumentation Program Representative.

DEER GROUP APPROVED

Earl W. Applekamp
COUNTY REMONUMENTATION
10-14-99

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2 1/2"X30" split base aluminum pipe with a 3" cap stamped to read: County Remonumentation, T48N, R41W, 1/4, S31, S32, 1999, P.S. 17610. I established three bearing trees and a Steel Marking Post.

| | | | | | | |
|------------------|-------|--------|---|--------------------|-------|--------|
| Nail in 6" Maple | S13°W | 14.40' | - | Nail in 16" Spruce | S76°E | 30.66' |
| Nail in 5" Maple | N18°E | 46.72' | - | 6' Steel Sign Post | West | 0.80' |



Signed by Earl W. Applekamp
Surveyor's Michigan License No. 17610

Date October 1, 1999